

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG20014722/EVD3E2  
**Date:** 20/01/2021

### REFERENCE

Insured/Claimant: CHOONG WENG YEW Policy No: 1900008302  
Date of Loss: 29/12/2020 Nature of Claim: OD Claim No: 4689486116SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH5778K**  
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHL8461  
Reg. Date: 28/01/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH000503  
Colour: Silver Odometer: 23097 km  
Engine Capacity: 1193 cc  
Market Value/New Car Price: S\$53,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,133.19	3,802.89	330.30	7.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,250.00	690.00	23.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,073.19</b>	<b>6,052.89</b>	<b>1,020.30</b>	<b>14.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	495.12	423.70	71.42	14.42
<b>Nett Amount (S\$)</b>	<b>7,568.31</b>	<b>6,476.59</b>	<b>1,091.72</b>	<b>14.42</b>

### INSPECTION

Date of Assignment: 30/12/2020  
Date Inspected: 30/12/2020 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER,FR RH	Dented	497.00 FL	*497.00 FL
2	1		*BRACKET,FR BUMPER,LH	Not Necessary	13.00 FL	*- FL
3	1		*BRACKET,FR BUMPER,RH	Broken	13.00 FL	*13.00 FL
4	1		*GARNISH,FR BUMPER,RH	Cut	127.00 FL	*127.00 FL
5	1		*FACE,FR BUMPER	Broken	703.00 FL	*703.00 FL
6	10		*CLIP,FR BUMPER	Necessary	40.00 FL	*40.00 FL
7	1		*HEADLAMP ASSY,RH	Broken	660.00 FL	*660.00 FL
8	1		*LAMP ASSY,FOG,FR LH	Not Necessary	303.00 FL	*- FL
9	1		*WHEEL,DISC	Cut	687.00 FL	*687.00 FL
10	1		*TANK,WINDSHIELD WASHER	Not Necessary	74.00 FL	*- FL
11	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
12	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
13	1		*ATTRAGE BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
14	6		*RIVET,FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,857.00</b>	<b>4,437.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (S\$)</b>	723.81	634.11
<b>Total Parts (S\$)</b>	<b>4,133.19</b>	<b>3,802.89</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON RH FRONT FENDER,FRONT BUMPER FACE,FRONT BODY KITS	New	1,350.00	900.00
2	PAINT WORK SPRAY RH FRONT FENDER,FRONT BUMPER,FRONT BODY KITS AND AFFECTED PORTION	New	1,050.00	1,050.00
3	PERFORM RUST PREVENTION	New	80.00	0.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK UISNG HI-SCAN PRO TEST UISNG HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING	New	30.00	30.00
8	RE-APPLY ZERTONA COATING	New	160.00	-
			<b>Gross Labour Cost (S\$)</b>	<b>2,940.00</b>
				<b>2,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >