



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Attrage 1.2 CVT.

Summary table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include KAX00008, Credit, 30/12/2020/ 10:33, QUD, 247 / DonBong, 61295.

Main itemized list table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like RENEW ACCIDENT DAMAGED PARTS ON RH FRONT FENDER, PAINT WORK SPRAY RH FRONT FENDER, etc.

Estimate

SURVEYOR NAME: Steve CLKK
SURVEYOR SIGNATURE: [Signature]
DATE: 30/12/20, 11.00am

Confirm & accepted by

DATE: PIP, Ry BK sy

REMARKS: 5 days
OO- NM Auth
EXCESS - ?

Summary of costs: Net 6,721.49, 7% GST on 470.50, Total Payable 7,191.99

LKK Auto Consultants hence notify the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts price is subject to change
Third party survey is on a "Warranty Basis"

No illegality of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing