

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 31 Dec 2020

Preliminary Advice

Vehicle No	: GBE7515K	Accident Date	: 11/12/2020
Make	: PEUGEOT PARTNER	Policy No.	: 0999993937
Assignment Date	: 30/12/2020	Excess	: S\$0.00
Date of Inspection	: 30/12/2020	Est. Duration of Repair	: 4
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,008.30
Revised Amount	:S\$	2,603.50
Check Items (Estimated)	:S\$	1,512.80
Total	:S\$	4,116.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	23,534.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,466.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE "TO SUPPLY AND PASTE ARTWORK ON RH BODY PANEL" WITH INSURED.