

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7521L

AAD2012-192

*Not Authorized
Return By paint
81342-18*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

29 DEC 2020

SHB7521L

JTDKB3FU103080857

TOYOTA

PRIUS

28/12/2020

CHINA

31/05/2019

PART

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 LENS AND BODY, REAR LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 LINER, REAR WHEEL HOUSE, RH

LIST

\$	CM	442.60	✓
\$	SL	576.30	X
\$	DIS	88.50	✓
\$	SL	123.70	X
\$	SL	502.00	X
\$	CM SL	451.80	X
\$	SL	241.90	X
\$	SL	139.80	X
TOTAL	\$	2,566.60	
25%	\$	641.65	
	\$	1,924.95	

Special Nett

- 1 REAR BUMPER SIDE CLIP
- 1 REAR FENDER LINER CLIP
- 1 TAIL LAMP CLIP
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER RETAINER CLIP

\$	na	60.00	✓
\$	SL	700.00	X
\$	na	85.00	X
\$	na	75.00	X
TOTAL	\$	920.00	

TOTAL PARTS \$ 2,844.95

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2012-192

SHB7521L

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>2001</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>4</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>2801</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	7,944.95	

(PART-BY-PART) Repair Days

10 Days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer