

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD138X**AAD2012-***Not Withheld
11 Sep 2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 DEC 2020**SHD138X**

VF1ABL15AUC283258

RENAULT

LATITUDE

26/12/2020

AIG

31/07/2017

PART**LIST**

1	BUMPER COVER FRT	\$	747.20	}	X
1	BUMPER RETAINER FRT LH	\$	101.40		
1	BUMPER FOG LAMP GRILLE LH	\$	207.21		
1	BUMPER BRACKET KIT FRT LH	\$	101.40		
1	BUMPER ABSORBER FRT	\$	394.68		
1	BUMPER BEAM FRT	\$	663.70		
1	AIR CLEANER BOX	\$	464.20		
1	AIR CLEANER HOSE	\$	175.85		
1	AIR CLEANER LOWER	\$	271.26		
1	DOOR MIRROR ASSY LH	\$	1,483.40		
1	FENDER PANEL FRT LH	\$	437.10	}	X
1	WHEELARCH FRT LH	\$	191.40		
1	DOOR PANEL FRT LH	\$	2,844.66		
1	DOOR REGULATOR FRT LH	\$	501.40		
1	DOOR REGULATOR MOTOR FRT LH	\$	758.10		
1	DOOR HINGE UPPER FRT LH	\$	274.50		
1	DOOR HINGE LOWER FRT LH	\$	300.55		
1	DOOR PANEL REAR LH	\$	2,844.66		
1	DOOR REGULATOR REAR LH	\$	450.60		
1	DOOR REGULATOR MOTOR REAR LH	\$	758.10		
1	DOOR HINGE UPPER REAR LH	\$	241.60	}	X
1	DOOR HINGE LOWER REAR LH	\$	169.90		
1	ROCKER PANEL OUTER LH	\$	1,184.99		
1	FENDER PANEL REAR LH	\$	1,933.20		

TOTAL \$ 17,501.06**10% \$ 1,750.11****\$ 15,750.95**

Trans-cab Auto Services Pte Ltd**AAD2012-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD138X**Special Nett**

1 BUMPER CLIP FRT	\$	na	90.00 X
1 BUMPER RETAINER CLIP FRT	\$	na	75.00 X
1 FENDER CLIP	\$	na	65.00 X
1 FENDER LINER CLIP	\$	na	65.00 X
1 DOOR TRIM CLIP	\$	na	70.00 X
1 DOOR MOULDING CLIP	\$	na	70.00 X
1 DOOR STICKER TRANSCAB	\$	na	100.00 60na
1 DOOR STICKER 65553333	\$	na	100.00 60na
1 DOOR STICKER CLASSIC	\$	na	100.00 15na
2 WINDSCREEN SEALANT	\$	na	150.00 X
1 WINDSCREEN MOULDING	\$	na	200.00 X
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00 X
1 TYRE	\$	na	300.00 X
1 RIM	\$	na	350.00 X

TOTAL \$ 1,865.00**TOTAL PARTS \$ 17,615.95****LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00 301
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 601
Putty and spray painting of the affected portion.	\$	1,400.00 8801
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00 4001
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD138X**AAD2012-**

To check steering geometry and computer wheel alignment	\$	220.00	X
TOTAL	\$	4,360.00	
Over All Total	\$	21,975.95	

DESCRIPTION OF CIRCUMSTANCES OF THE ACCIDENT (LUMPSUM) Repair Days**20 Days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: