ASS. REC. BY: Marcus REF: CC3/M	5620.014730/49.63		
	SIGNMENT		
From: Date: Estimated Cost:	Veh No: SZUSUSC Yr Regn: 15/11/17 Type M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /		
OD / TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (A)		
To Inspect Vehicle No: SLU \$425C	Make: Toyota C-MR MyR.60 1797		
at Workshop m/s £\$\mathcal{L}\$,	Colour Black A/C: Insured / Std / NI / NA		
of	S/ack mountaining		
Insured: (7BF 50937	Eng/No:		
Policy No. 29146062			
Claims No. 632720	632720 C/No: 2/X/0203.8564 Gen. Cond: Good/Fair/Poor/Burnt		
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or		
(Client's Record)			
Make of Veh:	Daniel Daniel of		
1	The second of th		
(Policy Condition)	Tyre Size: F:		
(Policy Condition) Remark: The veh had commenced its N/S			
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA /MIG / OHTSU / PIR / SUMI /		
Bal. or Market Value: & 70k	TOYO/YOKO or		
bail of Market Value.	Front Rear		
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. / mm R/Bal. / mm		
GIA / PR Seen: Consistent? : Yes or No	L/Bal. / mm L/Bal. / mm		
Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	D.O.A. $29/i\sqrt{20}$ D.O.I. $30/i\sqrt{20}$ Survey held at		
CA / REV / REP. / 24 HRS LYA SHHHY Vehicle: IN / OUT			
Date: Person Contacted:	Person Contacted:		
Date / Time Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision.			
Blind Spot monter 88162-DN	1540 (Bloka)		
/	,		
18/1/4 4/5 \$ 4500 Conf. and with Alm. CRED \$ 24897.90, 85%)			
(x/n/202 m. milled 1 the server			
(8/01/20 3-53 pu revised to traine Ngu Va Meinen.			
	, , , , , , , , , , , , , , , , , , , ,		
Date/Time, File Pass to? : Preli. Report	ays Of Repair:		
1) BI Mily : Final Report R	esurvey No. of Trip: / Survey Fee:		
Date/Time, File Return to?	Transportation:		
Add Fee:			
	: Interview (\$) Photos		
Report Format: MER-7P	: Tech. Invs (\$) Others		
Lump Sum / I, B:1: (\$ 4500)	:Weekend (\$		
	TOTAL		

(08/11/13) wef

FASTECH AUTO PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-,48, AUTO BAY SINGAPORE 417883

Suhaif to aswers.

30/1/20 1/5\$ 4500/ 4/ays-

VEHICLE No: SLU 8425C

1PC

1PC

1PC

REAR WINDSCREEN SEALANT

REAR END PANEL SEALANT

REAR LICENCE PLATE W/HOLDER

1PC	REAR WINDSCREEN N 7	\$1,488.10 🗙
1PC	REAR WINDSCREEN MOULDING	\$105.30 X
1PC	TAILGATE	\$1,650.00 📈
1PC	TAILGATE OUTER GARNISH	\$885.10 🗙
1PC	TAILGATE REAR LOGO 41	\$68.60 🗶
1PC	TAILGATE 'TOYOTA ' EMBLEM 41	\$60.20 🗙
1PC	TAILGATE 'C-HR' EMBLEM ~ 1	\$68.10 🗙
1PC	TAILGATE 'HYBRID SYNERGY DRIVE' LOGO	\$85.00 🗡
1PC	TAILGATE INNER LOCK	\$399.10
1PC	TAILGATE LOCK STRIKER 1	\$105.00 X
1PC	TAILGATE INNER TRIM BOARD 🔥 🥎	\$614.10 ×
1SET	TAILGATE INNER TRIM CLIPS	\$50.00 ×
2PCS	TAILGATE REFLECTORS @\$486.30 V/5 C/2 39510	\$972.60 (20
1PC	TAILGATE WEATHERSTRIP A 1	\$399.20 X
1PC	REAR BUMPER De 441.90	\$1,451.10
1PC	REAR BUMPER CENTRE PAD DE 456.10	\$885.10
1PC	REAR BUMPER TOW COVER 11	\$45.00 ×
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00 0/5 Bent 62.00	\$130.00 100
2PCS	REAR BUMPER REFLECTORS @\$105.00 0/5 c/e 65.00	\$210.00 126
2PCS	REAR BUMPER REFLECTOR GARNISHS @\$165.00 0/5 SCA 1/5.00	\$330.00 12 6
1PC	REAR BUMPER REINFORCEMENT Surf 322.70	\$665.10
1PC	REAR BUMPER LOWER CENTRE BRAKE LAMP 11	\$350.00 X
1PC	REAR END PANEL DO 716.00	\$1,100.20
1PC	REAR END PANEL TOP GARNISH	\$485.10 X
1PC	REAR END PANEL LOCK SENSOR	\$399.10 ×
1PC	REAR FLOOR PANEL M	\$1,480.10 🗶
1PC	REAR FLOOR PANEL TOP BOARD 1	\$811.10 🗴
1PC	REAR FLOOR PANEL TOOLS SPONGE	\$688.90 X
2PCS	REAR FENDERS @\$991.00	\$1,982.00
2PCS	REAR FENDER INNER TRIM BOARDS @\$499.20 ~ ~	\$998.40 ×
2PCS	REAR FENDER OUTER PROTECTORS @\$215.20 v (5 cm 221.10	\$430.40 17 6
2PCS	TAILLAMPS @\$755.80 0 15 C/c 600-20	\$1,511.60 10 C
2PCS	TAILLAMP HOUSING PANELS @\$266.10	\$532.20 ×
1PC	REAR BLIND SPOT MONITOR O/S REAR BLIND SPOT MONITOR BRACKET O/S Serf 60.00	\$1,800.00
1PC	REAR BLIND SPOT MONITOR BRACKET O/S Berf 60.00	\$122.00
1PC	REAR EXHAUST	\$1,420.10 ×
	(25%	\$24,777.90
	S.NETT	

17

11

11

\$50.00 \(\chi

\$50.00 X

\$50.00 X

TO CHECK WIRING	\$80.00 20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00 50
TO DISMANTLE & REFIX REAR WINDSCREEN	^^ \$120.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 fs
TO DISMANTLE & REFIX REAR EXHAUST	イ ク \$100.00 大
TO REMOVE & REPLACED , RECALIBRATE PROGRAM BLIND SPOT MONITOR	\$350.00 100
TO TRANSFER TAILGATE MECHANISM	へへ \$100.00 ×
TO SPRAY RUST PROOFING	\$120.00 3 ₀
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00 680
TO PUTTY & SPRAY PAINTING	\$1,600.00 900
TOTAL	\$29,397.90

1860

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: