

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20014738/UQD3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : GBJ5387A

Insured Vehicle No : GX1833Y

Date of Loss: 26/12/2020

Nature of Claim: TP

Claim No: CDMCG20002012

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ5387A**

Make & Model: FIAT FIORINO, 1.3 MJTD (A)

Engine No: 225A20006489508

Reg. Date: 24/05/2019 (Man. Year: 2017)

Chassis No: ZFA22500006H34376

Colour: White

Odometer: 32149 km

Engine Capacity: 1248 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,484.10	2,093.01	2,391.09	53.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	930.00	460.00	33.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,874.10	3,023.01	2,851.09	48.54
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	5,874.10	2,400.00	3,474.10	59.14
+ GST 7.00/7.00% (S\$)	411.19	168.00	243.19	59.14
Nett Amount (S\$)	6,285.29	2,568.00	3,717.29	59.14

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected: 30/12/2020 Inspected At:

Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto

Bay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2021)	
Parts:	N/A	FIAT FIORINO 1.3 MJTD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5387A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Grazed	1,245.50 F	*1,021.10 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
3	1		*FRONT FENDER	Dented	780.00 F	*780.00 FL
4	1		*FRONT DOOR	Repair	1,612.80 F	*- FL
5	1		*FRONT DOOR OUTER PROTECTOR	Grazed	207.80 F	*207.80 FL
6	1		*FRONT WHEEL HUB-CAP	Repair	225.00 FS	*- FS
7	1		*FRONT DOOR ROC STICKER	Necessary	48.00 FS	*40.00 FS
8	1		*FRONT DOOR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,484.10	2,298.90
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	205.89
Total Parts (\$\$)	4,484.10	2,093.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
3	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING SNF MECHANISMS	New	80.00	0.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC	New	500.00	480.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	680.00	400.00
Gross Labour Cost (\$\$)			1,390.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >