

AIG

Vehicle number	SFT5007Y
Make / Model	TOYOTA/COROLLA
Chassis number	MR053ZEE106155932
Accident date	27/12/20
Reference	2012-49

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	BOOTLID	822.25 <i>bt</i> ✓
1	BOOTLID EMBLEM LOGO	69.00 <i>nei</i> ✓
1	BOOTLID EMBLEM -COROLLA	46.00 <i>nei</i> ✓
1	BOOTLID EMBLEM - ALTIS	50.60 <i>nei</i> ✓
1	BOOTLID EMBLEM - 1.6	61.20 <i>nei</i> ✓
1	BOOTLID GARNISH	270.25 <i>x n</i> ✓
2	BOOTLID LAMP	763.70 <i>x n</i> ✓
2	BOOTLID LAMP INNER SEAL	56.00 <i>x n</i> ✓
1	BOOTLID LOCK	380.19 <i>bt</i> ✓ <i>111.90</i>
1	BOOTLID LOCK COVER	55.00 <i>mt</i> ✓
2	BOOTLID HINGE	131.10 <i>RP</i> ✓
1	BOOTLID INNER TRIM	396.70 <i>x n</i> ✓
2	BOOTLID STOPPER	23.00 <i>nei</i> ✓
1	END PANEL <i>photo</i>	672.75 <i>bt</i> ✓ <i>580.</i>
1	END PANEL TOP GARNISH	241.50 <i>? photo</i> <i>x n</i> ✓
1	REAR BUMPER	557.75 <i>de</i> ✓
2	REAR BUMPER REFLECTOR	71.30 <i>x n</i> ✓
2	REAR BUMPER RETAINER	138.00 <i>nei</i> ✓
1	REAR BUMPER SPONGE	149.50 <i>one</i> ✓
2	REAR BUMPER DAMPER	181.70 <i>? x n</i> ✓
2	REAR TAILLAMP <i>e 340mm</i>	828.36 <i>ire</i> ✓ <i>680.</i>
1	REAR EXHAUST SILENCER	702.65 <i>x</i> ✓
2	REAR EXHAUST MOUNTING	40.00 <i>x</i> <i>yn</i> ✓
2	REAR FENDER INNER TRIM	770.50 <i>x</i> ✓
		7479.00
Less 25 %		1869.75
Subtotal		5609.25
Balance C/F		5609.25
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP	30.00 <i>nei</i> ✓
1 SET	REAR FENDER INNER TRIM CLIP	30.00 <i>x n</i> ✓
1 SET	END PANEL TOP GARNISH CLIP	30.00 <i>10 nei</i> ✓
1 SET	REAR REVERSE SENSOR	400.00 <i>200mm</i> ✓
1	REAR NUMBER PLATE	80.00 <i>x n</i> ✓
1 SET	STICKER	60.00 <i>H0 nei</i> ✓
1	JOINT SEALANT	120.00 <i>4 only</i> ✓
Subtotal		750.00

3344.20
2508.15

320

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30.
2	REMOVE , REFIT REAR LINING, TRIM AND GARNISH	150.00 60.
3	REMOVE AND RENEW REAR REVERSE SENSOR	100.00 30.
4	REMOVE AND RENEW REAR EXHAUST	120.00 X 20.
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60
6	PANEL BEATING ON AFFECTED AREAS	1400.00 700.
7	SPRAY PANTING ON AFFECTED AREAS	1200.00 700
8	APPLY ANTI RUST ON AFFECTED AREAS	120.00 30
Subtotal		3350.00
Grand total		9709.25

1660

Taughin 97495749

'WP' 29/12/20 c 1300m

c/s resurvey after repair

taughin c 11 hours. am.

5 days.

2508.15

320

1660

4438.15

c/s 3550

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: