



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

29/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chiam
Jashin

Accident date: 16/12/2020

Estimated repair cost for vehicle no: SJP8037P TOYOTA PREMIO 1.5F A 09'

CHASSIS: NZT2603038178

S/n	Qty	Items	U/price	Amount
1	1	Rear Bootlid <i>Repair</i>		\$1,189.50
2	1	Rear Bootlid R/H Side Reflector <i>cut</i>		\$285.00
3	1	Rear Bootlid Premio Logo <i>for</i>		\$64.00
4	1	Rear Bootlid Emblem Logo		\$58.00
5	1	Rear Bootlid P Logo		\$35.00
6	1	Rear R/H Tail Lamp <i>cut</i>		\$480.10
7	1	Rear Bumper <i>behind</i>		\$1,189.50
8	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00
9	1	Rear Bumper Reverse Sensor <i>dayd</i>		\$380.00
10	2	Rear Bumper Side Retainer <i>NEG</i>	\$89.50	\$179.00
11	1	Rear End Panel <i>Repair</i>		\$561.00
12	1	Rear End Panel Top Garnish <i>behind</i>		\$371.00

Spare Tyre Panel Top Cover
behind

288

Subtotal :- \$4,844.10

2408

18065

S.N: 220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour charges

To remove & refit cushion	\$280.00 40
To remove & refit rear camera	\$180.00 X
To check wiring	\$100.00 30
Tuff kote	\$150.00 40
Panel beating	\$600.00 300
Spray painting	\$600.00 600

Subtotal :- \$1,910.00

Total:- \$6,754.10

Total: 3236.15

L/S: 2.6K.
24 Days

2.6K.
04 Apr