



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

29/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chiam.
Jashin.

Accident date: 16/12/2020

Estimated repair cost for vehicle no: SJP8037P TOYOTA PREMIO 1.5F A 09'

CHASSIS: NZT2603038178

S/n	Qty	Items	U/price	Amount
1	1	Rear Bootlid <i>Repair</i>		\$1,189.50 ✓
2	1	Rear Bootlid R/H Side Reflector <i>cut</i>		\$285.00 ✓
3	1	Rear Bootlid Premio Logo <i>for</i>		\$64.00 ✓
4	1	Rear Bootlid Emblem Logo		\$58.00 ✓
5	1	Rear Bootlid P Logo		\$35.00 ✓
6	1	Rear R/H Tail Lamp <i>cut</i>		\$480.10 ✓ 371
7	1	Rear Bumper <i>Deland</i>		\$1,189.50 ✓ 855
8	8	Rear Bumper Clip <i>NW</i>	\$6.50	\$52.00 30
9	1	Rear Bumper Reverse Sensor <i>Dayd</i>		\$380.00 ✓ 220 (SN)
10	2	Rear Bumper Side Retainer <i>NEG</i>	\$89.50	\$179.00 ✓
11	1	Rear End Panel <i>Repair</i>		\$561.00 ✓
12	1	Rear End Panel Top Garnish <i>Deland</i>		\$371.00 ✓ 233
<i>Spare Tyre Panel Top Covers</i> <i>Deland</i>				288 ✓
Subtotal :-				\$4,844.10

2408

18065

S.N: 220

Labour charges

To remove & refit cushion	\$280.00 40
To remove & refit rear camera	\$180.00 X
To check wiring	\$100.00 30
Tuff kote	\$150.00 40
Panel beating	\$600.00 300
Spray painting	\$600.00 600

Subtotal :- \$1,910.00

Total:- \$6,754.10

Total: 3236.15

L/S: 2.6K.
24 Days

2.6K.
04 Apr