

EuroAutomobile Pte Ltd



AIG Asia Pacific Insurance Pte Ltd
AIG Building 78 Shenton Way
#07-16
Singapore 079120

REG. NO : SMK9428D
INSURED : MATTHEW SOON WEE KEAT
MODEL : ALFA ROMEO - STELVIO
CHASSIS NO : ZARPAH1VGN3K7C53599
POLICY NO : GA467186/1
EXCESS : -
D.O.A. : 12/12/2020
Third Party Reg Number : SKJ7734L
Third Party Insurance : AIG Insurance

Date: 15/12/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NO	PARTS REPLACEMENT	QTY	PART NO	LIST PRICE	NETT PRICE
1	FRONT BUMPER	1	50551535	\$2,490.00	\$2,490.00
2	FRONT BUMPER CLIP SET	1	SET	\$404.00	\$404.00
3	FRONT BUMPER REINFORCEMENT	1	50535771	\$113.00	\$113.00
SubTotal Parts					\$3,007.00

2894

S/NO	LABOUR	
1	R&R ONE FRONT BUMPER (NEW PART REPLACEMENT)	\$750.00
2	PAINTING ONE FRONT BUMPER PANEL	\$750.00
3	CALIBRATION OF ACC/SPEED SENSOR - ADD JOB AFTER REPLACEMENT OF FRONT BUMPER	\$480.00
4		
SubTotal Labour		\$1,980.00

1980

S/NO	SPECIAL NETT	
1	PAINT PROTECTION FILM - FRONT BUMPER PANEL	\$1,300.00
	FRONT NUMBER PLATE	\$30.00
Special Nett Total		\$1,330.00

- invoice.

Cost of Repair
Parts \$3,007.00
Labor \$1,980.00
Special Nett \$1,330.00
SubTotal \$6,317.00
Total inc. GST \$6,759.19

3 Days.
part by part.
before paint photos. / After repair photos.

4874

Yours faithfully.



Surveyed by:

Contact No:

Surveyed date:

Excess:

Authorised on:

Resurvey:

Guo Qiang

82880282

04/1/2021

yes.

Guo Qiang @ lkk auto. com

EuroAutomobile Pte Ltd
(200201004E)

24, Leng Kee Road #01-03
Singapore 159096
Tel : (65) 6567 5252
Fax : (65) 6566 5252