


Yong Sing Estimate Repair

Vehicle Registration Number : SKR 8641 Y
Make / Model : BMW
Chassis No :
Year of Manufacture :
Registration Date :
Type of Repair (TP/OD/WS) : TP
Date/Time of Accident :
Rental Vehicle : Yes ☒ No
Remark :

Case Ref. No. :
The damages on the vehicle are as indicated in the following diagram :



Front
Rear
Left N/S
Right O/S
Vehicle Diagram

	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 1,500.00	\$ -
Total Spray Painting Cost	\$ 480.00	\$ -
Total Spare Parts Cost	\$ 5,616.63	\$ -
Other Charges	\$ 260.00	\$ -
TOTAL	\$ 7,856.63	\$ -
Lump Sum Repair, if any : \$ -		
No. of Repair Days	(5) days	() days

SURVEYOR'S Remark

2 Days. Lump Sum Repair / After repair photos
Gano Qiang - 82880282
11/1/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR FRONT PORTION	\$1,500.00	250 250
Total Labour Cost	\$1,500.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY FRONT BUMPER	\$ 300.00	250 250
TO RESPRAY FRONT REINFORCEMENT	\$ 180.00	X NN
Total Spray Painting Cost	\$ 480.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO CHECK WIRING SYSTEM AND FUNCTION	\$ 100.00	X
TO REMOVE SUNDRY PARTS	\$ 100.00	X
TO WASH AND VACUUM	\$ 60.00	X 5NN
Total Other Costs	\$ 260.00	\$0.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (10%)	Final Price (\$)	Repair @ Replace (/)	Repair @ Replace (/)	REMARK
1	FRONT BUMPER		1	\$ 1,255.40	10%	\$ 1,129.86	Replace		
2	BUMPER CLIPS		10	\$ 50.89	10%	\$ 45.80	Replace		
3	FRONT RETAINER BUMPER SIDE LH		1	\$ 107.30	10%	\$ 96.57	Replace		
4	FRONT RETAINER BUMPER SIDE RH		1	\$ 107.30	10%	\$ 96.57	Replace		
5	TOWING COVER FRONT		1	\$ 117.80	10%	\$ 106.02	Replace		
6	FRONT GRILLE LH		1	\$ 238.44	10%	\$ 214.60	Replace		
7	FRONT GRILLE RH		1	\$ 238.44	10%	\$ 214.60	Replace		
8	FOG LAMP COVER RH		1	\$ 221.32	10%	\$ 199.19	Replace		
9	FOG LAMP RH		1	\$ 289.86	10%	\$ 260.87	Replace		
10	FRONT BUMPER CENTRE LOWER GRILLE		1	\$ 329.67	10%	\$ 296.70	Replace		
11	FRONT BUMPER REINFORCEMENT		1	\$ 546.12	10%	\$ 491.51	Replace		
12	FRONT BUMPER ABSORBER		1	\$ 202.87	10%	\$ 182.58	Replace		
13	FRONT NUMBER PLATE W/ FRAME		1	\$ 30.00	0%	\$ 30.00	Replace		
14	FRONT NUMBER PLATE BASE		1	\$ 180.13	10%	\$ 162.12	Replace		
15	FRONT EMBLEM "BMW"		1	\$ 180.13	10%	\$ 162.12	Replace		
16	HEADLAMP FRONT RH		1	\$ 2,141.70	10%	\$ 1,927.53	Replace		
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
TOTAL MATERIALS \$ 6,237.37						\$ 5,616.63			

842
30(SN)

86.05
86.05

40(SN)
83

Surveyor Remark:

Adjusted by Surveyor, if applicable

1097-1
100% 987.39
SN: 70
Total: 1557.39
20%: 1250