



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101738

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 18/03/2021
Reference CC4/FCI20014766/T1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMM 4033G
Insured Veh. SHA 4247D
Claim No. D21000040MFSH
Policy No. D-20094922MFSH
Accident Date 27/12/2020
Inspection Date 05/01/2021

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20014766/T1ea3q2 Date: 18/03/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4247D	Veh. Inspected	SMM 4033G	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D21000040MFSH	Excess (\$)	0.00	
Assign From	CHRIS LIM	Assign Date	30/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF 1.4	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WWWZZZAUZKW022383	Colour	YELLOW	
Odometer	17600 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	PIRELLI	6 mm	
L/H Front Tyre	225/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2020	Inspection Date	05/01/2021	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 4033G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED REAR BUMPER (SN)	DEFORMED	1,165.55	1,165.55
1	REAR DIFFUSOR SATIN BLACK (SN)	NOT NECESSARY	315.27	-
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	619.61	-
1	ATTACHMENT STRIP RR CTR BRACKET (SN)	NECESSARY	64.97	64.97
1	GUIDE PIECE LHR TAILLIGHT BRACKET (SN)	NOT NECESSARY	37.46	-
1	GUIDE PIECE LHR SIDE BRACKET (SN)	NOT NECESSARY	37.46	-
1	SENSOR BRACKET (SN)	NECESSARY	12.13	12.13
1	SENSOR BRACKET (SN)	NECESSARY	12.13	12.13
1	SENSOR BRACKET (SN)	NECESSARY	12.60	12.60
1	SENSOR BRACKET (SN)	NECESSARY	12.13	12.13
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	75.94	75.94
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	59.40	59.40
1	REFLECTOR LHR (SN)	NOT NECESSARY	71.19	-
			2,495.84	1,414.85
	<u>LABOUR</u>			
	LABOUR .		2,520.00	840.00
	SPRAY PAINTING .		2,400.00	800.00
	DIAGNOSTIC AND PROGRAMMING .		480.00	480.00
	CHECK SHORT CIRCUIT /HARNESS REPAIR .		280.00	280.00
			5,680.00	2,400.00
	GRAND TOTAL		8,175.84	3,814.85
	RECOMMENDED COST OF REPAIRS			3,814.85

Report Ref No. CC4/FCI20014766/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4033G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4033G

RE-INSPECTION

