



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20008744/Etd3e2-1	
			Date: 26/01/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3313S	Veh. Inspected	GBA 9193M
	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT20080147	Excess (\$)	0.00
	Assign From	CARINE KHEK	Assign Date	30/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN CADDY	c.c	1896
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	WV1ZZZ2KZ8X109783	Colour	BLACK
	Odometer	241195 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	GOODYEAR	5 mm
	L/H Front Tyre	185/65 R15	GOODYEAR	5 mm
	R/H Rear Tyre	185/65 R15	GOODYEAR	5 mm
	L/H Rear Tyre	185/65 R15	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/08/2020	Inspection Date	20/08/2020
	Survey held at	Blk 5 Defu Lane 10 #01-582 Singapore 539186		
	Repairer	HENG MOTOR SERVICES		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	