

# Performance Motors Limited

A Sime Darby Motor Company  
 U.S. Reg. No. 1974215596 GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255289)

323, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159441  
 Fax: 64797772

290, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax: 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax: 64796601 (AfterSales)  
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

29 DEC 2020

Estimate No. : b1 57062	Page No. : 1 of 5
Date Estimated : 29/12/2020	
Prepared By : Brandon Chan Eng Meng	

- ESTIMATE REPAIR FOR - Roy Bidhan Chandra 3 Bedok Reservoir View. (S)478927 Aquarius By The Park #18-03 SINGAPORE 478927	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY558H	NBATS720409C54030	08/09/2020	X3 sDrive20i	0

DESCRIPTION	VALUE
To replace rear bumper, rear bootlid, rear bumper carrier, attachment item cause by accident.	1700 2,550.00
To spray paint rear bumper, rear bootlid.	1805 2,006.00
To remove & install rear windscreen glass.	nn X 676.00
To conduct water leak tests.	nn X 75.00
To supply and install rear windscreen solar film.	nn X 531.00
To check electrical wiring system and lighting at the rear section for proper function.	150 177.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	nn X 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	nn X 118.00
Sundries	80? 150.00

Total Labour 1: 6,991.00

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TRIM CHROME D=90MM	1	124.00	125.85 <del>124.00</del>
TRUNK LID	1	1,973.35	RV 1,973.35
REAR BUMPER CARRIER	1	743.50	743.50
LH SIDE GUIDE FOR BUMPER	1	58.25	58.25
LH BUMPER GUIDE	1	61.35	61.35

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 57062**  
 Date Estimated : **29/12/2020**  
 Prepared By : **Brandon Chan Eng Meng**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY558H	WBATS720409C54030	08/09/2020	X3 sDrive20i	0

DESCRIPTION	QTY	PRIC	VALUE
Abrasion gua	1	4.40	4.40
REAR BUMPER PANEL PRIMED (M/PMA)	1	1,555.40	1,555.40
REAR BUMPER BOTTOM TRIM PANEL (M)	1	370.35	370.35
PLAQUE 82MM	1	71.60	71.60
LETTERING X3	1	64.45	64.45
LETTERING S DRIVE 20I	1	96.65	96.65
BUMP STOP	10	3.20	32.00
LH REFLECTOR	1	38.85	38.85
ULTRASONIC SENSOR PHYTONIC BLUE (WC	2	381.90	763.80
ULTRASONIC TRANSDUCER DARK SHADOW	1	370.00	370.00
DECOUPING RING PDC TORQUE CONVERTER	65.15	5.10	30.90
SET ADHESIVE PADS FOR ACE 2.0	1	43.65	43.65
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85

Total Parts : 6,719.30

245/50K19 Yo ho

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 5/1/21 21/1/21 Excess S\$ \_\_\_\_\_

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 97445714 Authorised Yes / No \_\_\_\_\_

Authorised Date UP Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail Tanpin@lkkauto.com

No. of Working Days Recommend 5 days

**LKK Auto Consultants hence notify**

- the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Labour 1	:	6,991.00
Parts	:	6,719.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	959.72
<b>Grand Total</b>	:	<b>14,670.02</b>



Authorised by Repairer

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE \*\*