

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE REPAIR QUOTATION

FIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 24/12/2020@1220HRS
VRN : SKB3316D
MODEL : Toyota Wish
TP VRN : SHA2566X

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
PARTS REPLACEMENT				
1. Body Repair				
1 Rear Bumper	1	\$ 595.00	\$ 595.00	491.9
2 Rear Bumper Clips	10	\$ 5.50	\$ 55.00	
3 Rear Bumper Outer Bracket LH/RH	2	\$ 48.00	\$ 96.00	X
4 Rear Bumper Taillamp Bracket LH/RH	2	\$ 55.00	\$ 110.00	X
5 Rear Bumper Reflector LH/RH	2	\$ 48.00	\$ 96.00	X
6 Rear Reverse Sensor	1	\$ 195.00	\$ 195.00	
7 Rear Exhaust	1	\$ 1,010.00	\$ 1,010.00	X
8 Tailgate	1	\$ 1,400.00	\$ 1,400.00	1175
9 Tailgate Lock	1	\$ 425.00	\$ 425.00	361.6
10 Tailgate Hinge LH/RH	2	\$ 65.00	\$ 130.00	X
11 Tailgate Damper LH/RH	2	\$ 275.00	\$ 550.00	X
12 Tailgate Reflector LH/RH	2	\$ 195.00	\$ 390.00	X
13 Tailgate Chrome Garnish	1	\$ 195.00	\$ 195.00	X
14 Tailgate Toyota Logo	1	\$ 55.00	\$ 55.00	
15 Taillamp LH/RH	2	\$ 245.00	\$ 490.00	X
16 End Panel	1	\$ 536.70	\$ 536.70	453.9
17 End Panel Upper Garnish	1	\$ 285.00	\$ 285.00	X
18 Rear Spare Tyre	1	\$ 650.00	\$ 650.00	X
19 Rear Spare Tyre Holder	1	\$ 325.00	\$ 325.00	X
20 Sealant	1	\$ 45.00	\$ 45.00	
Buzzer sensor	1	\$ 45.00	\$ 45.00	
Discount -25%			\$ (1,897.18)	
Buzzer sensor wire	1	\$ 45.00	\$ 45.00	
Windscreen moulding	1	\$ 45.00	\$ 45.00	
TOTAL			\$ 5,736.52	

2. Labor Charges

1 Remove, repair and replace parts for affected areas	750	\$ 1,000.00
2 Spray paint on the affected areas	750	\$ 1,000.00
3 Check wiring, re-align taillamps ensure proper functioning	100	\$ 100.00
4 Remove & reinstall 2 pieces of bumper sensors	40	\$ 120.00
5 Remove & Refit Rear End Panel Lining & Garnish To Faciliate Repair	60	\$ 150.00
6 Remove & Refit Rear Windscreen To Faciliate Repair	120	\$ 180.00
7 Dismantle & Transfer Bootlid Fitting & Mechanism To New Bootlid	60	\$ 180.00
8 Remove & Reinstall Rear Reverse Camera	40	\$ 120.00
9 Remove & Replace Exhaust Pipe To Faciliate Repair	150	\$ 150.00
Sub Total		\$ 3,000.00

Grand Total : \$ 8,736.52
Add 7% GST : \$ 611.56
Nett Total : \$ 9,348.08

repair days: 7

Zero

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

4 Days.

Upsum repair

After repair photos.

Gmo Q:arl - 82880282

30/12/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: