

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305441710  
 REGN NO : SHD3156Z  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 16.06.2016  
 DATE/TIME IN : 30.12.2020 10:10  
 ACCIDENT DATE : 30.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00 20.00 884.80 <i>de ✓</i>
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00 20.00 182.40 <i>XSR ✓</i>
0003	04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	119.50 20.00 95.60 <i>? XSR ✓</i>
0004	04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	10 L	22.00 20.00 17.60 <i>un ✓</i>
0005	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00 2.00- 50.00 <i>turn ✓</i>
				SUB-TOTAL : 1,230.40

*952.40*

JOB NATURE

0000	PB	PANEL BEATING		300.00 <del>300.00</del> <i>280</i>
0001	SP	SPRAYPAINT CHARGE		200.00 ✓
0002	L	REMOVE/REFIX REVERSE SENSOR		80.00 <i>60</i>
0003	20-05	RENEW ADVERTISEMENT STICKER-Bumper		50.00 ✓
				SUB-TOTAL : 630.00

*590*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Rasul*  
*Hp 90000068*  
*2 days*  
*48*  
*30/12/2020 @1435*  
*Resur after repair*

*952.40*  
*590.00*  


---

*1542.40*  
*20%*  
*1233.92*  


---

*45-1250*