

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1028/2020/NS
DATE : 30-Dec-20
WIP : 64923

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR ANG CHEE HIAN(HONG ZHIXIAN)
ADDRESS : BLK 317 JURONG EAST STREET 31
#03-10
SINGAPORE 600317
TELEPHONE : HP +65 91503369
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : SMS 9125 K
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 20/3/2020
ENGINE NO : CHZ C32219
CHASSIS NO : WAUZZZ8V4KA113980
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Dec-20
PLACE OF ACCIDENT : BUKIT TIMAH ROAD JUNCTION TO SERANGOON ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9125 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	✓
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 1,800.00	? X
SUB TOTAL LABOUR CHARGES		: \$ <u>2,710.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9125 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 2,800.00	1500 ✓
6	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR COVER.	S 3,900.00	1800 ✓ 550 x 3 = 1650 Mirror = 150.
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N S 520.00	? 280 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		: <u>S 10,122.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9125 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Deformed</i>	\$	1,987.00 ✓	<i>1589.60</i>
2 FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	185.00 x	
3 FRONT BUMPER GUIDE SECTION - RH <i>Neu</i>	\$	38.00 x	
4 FRONT BUMPER CLOSING ELEMENT - RH <i>Neu</i>	\$	293.00 x	
5 FRONT BUMPER COVER TRIM - RH <i>Xbl n</i>	\$	161.00 x	
6 WHEEL HOUSING LINER ADAPTER - RH <i>Not nec</i>	\$	37.00 ? x	
7 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>	\$	530.00 x	
8 FRONT BUMPER AIR GUIDE GRILLE - RH <i>Neu</i>	\$	186.00 +	
9 FRONT FENDER - RH <i>Distorted</i>	\$	841.00 ✓	<i>680.40</i>
10 FRONT FENDER ATTACHMENT PARTS <i>Neu</i>	\$	71.00 x	
11 FRONT FENDER BRACKET - INNER <i>Neu</i>	\$	27.00 ? x	
12 FRONT FENDER BRACKET - OUTER <i>? Bent Best</i>	\$	38.00 ? ✓	<i>30.72</i>
13 FRONT FENDER BRACE <i>Neu</i>	\$	95.00 ? x	
14 FRONT FENDER INSULATION - RH <i>Neu</i>	\$	42.00 ? x	
15 WHEEL HOUSING LINER SEAL - RH <i>Neu</i>	\$	34.00 ? x	
16 FRONT FENDER CLOSING ELEMENT - RH <i>Neu</i>	\$	33.00 ? x	
17 WHEEL HOUSING LINER - RH <i>? Deformed</i>	\$	167.00 ? ✓	<i>134.80</i>
18 WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	\$	88.00 x	
19 BONNET EDGE PROTECTION <i>Neu</i>	\$	28.00 x	
20 FRONT DOOR - RH <i>Dented</i>	\$	2,494.00 ✓	<i>1995.20</i>
SUB TOTAL SPARE PARTS	:	\$ 7,375.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9125 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 FRONT DOOR OUTER SEAL - RH <i>Neu</i>	NEC	\$ 159.00	✓ 128.40
22 BONDING AGENT <i>Neu</i>	NEC	\$ 47.00	? X
23 CLEANING SOLUTION <i>Neu</i>	NEC	\$ 65.00	? X
24 FRONT DOOR ATTACHMENT PARTS <i>Neu</i>	\$	238.00	X
25 FRONT DOOR CATCH <i>Neu</i>	\$	104.00	? X
26 EXTERIOR MIRROR MOUNTING - RH <i>Cat</i>	\$	1,013.00	✓ 819.70
27 MIRROR CAP - RH <i>Cat</i>	\$	148.00	✓ 118.40
28 MIRROR GLASS - RH <i>Neu</i>	\$	1,644.00	X
29 CORNER TRIM - RH <i>Neu</i>	\$	45.00	X
30 WINDOW SLOT SEAL - RH FRONT <i>Neu</i>	\$	305.00	X
31 WINDOW GUIDE TRIM STRIP - RH <i>Neu</i>	\$	254.00	X
32 TYRE PRESSURE DATA PLATE <i>Neu</i>	\$	28.00	✓ 24
33 LED HEADLIGHT - RH <i>Cat</i>	\$	5,455.00	✓ 4364
34 LIFT CYLINDER - RH <i>Neu</i>	\$	141.00	X
35 TRACK CONTROL ARM <i>Neu</i>	\$	363.00	? X
36 WHEEL BEARING HOUSING <i>Neu</i>	\$	563.00	? X
37 WHEEL BEARING <i>Neu</i>	\$	485.00	? X
38 GUIDE JOINT - TH <i>Neu</i>	\$	120.00	? X
39 COUPLING ROD <i>Neu</i>	\$	93.00	? X
40 GAS SHOCK ABSORBER <i>Neu</i>	\$	259.00	? X
SUB TOTAL SPARE PARTS	:	\$ 11,529.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9125 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 TRACK ROD <i>Neu</i>	\$	89.00	? X
42 TIE ROD END <i>Neu</i>	\$	122.00	? X
43 FRONT ALUMINIUM RIM - RH <i>at</i>		TBC	✓ 850
44 SUNDRIES <i>Neu</i>	\$	350.00	? 25.84 ✓
TOTAL SPARE PARTS	:	\$ 19,465.00	
TOTAL LABOUR CHARGES	:	\$ 10,122.00	
GRAND TOTAL	:	\$ 29,587.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Lj
30/12/20

Not Authorised, 06 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT