

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1022/2020/NS
DATE : 29-Dec-20
WIP : 64465

VEHICLE IS NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS KAREN TEO
ADDRESS : 53 HUME AVENUE
#01-04
SINGAPORE 598751
TELEPHONE : HP +65 92788177
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700023569-03
VEHICLE NO : **SLQ 3049 J**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 4/7/2017
ENGINE NO : CVN 038975
CHASSIS NO : WAUZZZF43HA164129
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Dec-20
PLACE OF ACCIDENT : T-JUNCTION BETWEEN BISHAN ST 11 AND BISHAN ST 12



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 3049]

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID LICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	X
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	X
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS AND REAR WINDSCREEN.	S/N \$ 400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS AND REAR WINDSCREEN.	S/N \$ 200.00	X
5	TO DISLodge AND REINSTALL RER WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: <u>\$ 2,960.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLO 3049]

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	X
7	TO DISMANTLE REAR BUMPER. TO REPAIR RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,250.00	1000
8	TO RESPRAY RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DOORENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 4,750.00	1100
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: <u>\$ 14,552.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3954 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR FENDER - RH <i>Repair</i>		\$ 2,644.00	+
2 REAR WINDSCREEN <i>new</i>		\$ 1,141.00	+
3 1/4 GLASS - RH <i>new</i>		\$ 609.00	+
4 PRIMER <i>new</i>		\$ 19.00	+
5 WHEEL HOUSING LINER - RH <i>new</i>		\$ 237.00	+
6 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 90.00	+
7 REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	+
8 1/4 GLASS SEALANT <i>new</i>	S/N	\$ 100.00	+
9 METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	+
10 STONE CHIP <i>new</i>	S/N	\$ 180.00	+
11 CAVITY WAX <i>new</i>	S/N	\$ 140.00	+
12 ACRYLIC SEALANT	S/N	\$ 180.00	+
13 SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 6,120.00	
TOTAL LABOUR CHARGES	:	\$ 14,552.00	
GRAND TOTAL	:	\$ 20,672.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *30/12/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *NE authorised, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT