

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1022/2020/NS
DATE : 29-Dec-20
WIP : 64465

VEHICLE IS NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian,

5 days - ok - Jy - 2 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS KAREN TEO
ADDRESS : 53 HUME AVENUE
#01-04
SINGAPORE 598751
TELEPHONE : HP +65 92788177
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700023569-03
VEHICLE NO : SLQ 3049 J
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 04/07/2017
ENGINE NO : CVN 038975
CHASSIS NO : WAUZZZF43HA164129
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Dec-20
PLACE OF ACCIDENT : T-JUNCTION BETWEEN BISHAN ST 11 AND BISHAN ST 12



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 3049 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID LICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS AND REAR WINDSCREEN.	S/N \$ 400.00	
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS AND REAR WINDSCREEN.	S/N \$ 200.00	
5	TO DISLODGE AND REINSTALL RER WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	
SUB TOTAL LABOUR CHARGES		: \$ 2,960.00	\$ -



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 3049 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	
7	TO DISMANTLE REAR BUMPER. TO REPAIR RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,250.00	\$ 1,000.00
8	TO RESPRAY RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DOORENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 4,750.00	\$ 1,100.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 14,552.00	\$ 2,292.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3954 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR FENDER - RH		\$	2,644.00	
2	REAR WINDSCREEN		\$	1,141.00	
3	1/4 GLASS - RH		\$	609.00	
4	PRIMER		\$	19.00	
5	WHEEL HOUSING LINER - RH		\$	237.00	
6	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	90.00	
7	REAR WINDSCREEN SEALANT	S/N	\$	200.00	
8	1/4 GLASS SEALANT	S/N	\$	100.00	
9	METAL FILLER POWDER	S/N	\$	280.00	
10	STONE CHIP	S/N	\$	180.00	
11	CAVITY WAX	S/N	\$	140.00	
12	ACRYLIC SEALANT	S/N	\$	180.00	
13	SUNDRIES		\$	300.00	
TOTAL SPARE PARTS		:	\$	6,120.00	\$ -
TOTAL LABOUR CHARGES		:	\$	14,552.00	\$ 2,292.00
GRAND TOTAL		:	\$	20,672.00	\$ 2,292.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED