

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20014789/QQD3Q2

**Date:** 10/02/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00099252002
<b>Claimant Vehicle No :</b>	SKE7266Y	<b>Insured Vehicle No :</b>	SJC4020G
Date of Loss:	24/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D205137/C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE7266Y	Engine No:	G4FGCU516364
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMCU485133
Reg. Date:	29/03/2012 (Man. Year: 2012)	Odometer:	368271 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,130.72	1,165.92	1,964.80	62.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,730.72</b>	<b>1,965.92</b>	<b>2,764.80</b>	<b>58.44</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,550.00</b>		
<b>(\$\$)</b>	4,730.72	1,550.00	3,180.72	67.24
<b>+ GST 7.00/7.00% (\$\$)</b>	331.15	108.50	222.65	67.24
<b>Nett Amount (\$\$)</b>	<b>5,061.87</b>	<b>1,658.50</b>	<b>3,403.37</b>	<b>67.24</b>

### INSPECTION

Date of Assignment:	31/12/2020	
Date Inspected:	31/12/2020 Inspected At:	Af & Cars Pte Ltd (HQ) 39 Woodlands Close, #01-34/35, Mega @ Woodlands Singapore 737856
Estimated Period of Repair:	3.0 days	

**Adjuster:** OI SUN PIN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2021)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE7266Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	732.70 FL	*- FL
2	2		*REAR BOOT LID HINGE L/R	Serviceable	317.60 FL	*- FL
3	1		*REAR BOOT LID MECHANISM LOCK	Jammed	134.50 FL	*134.50 FL
4	1		*REAR BOOT LID MECHANISM LOCK STRIKER	Serviceable	74.90 FL	*- FL
5	1		*REAR TAIL LAMP L/R	N/s Cracked	842.60 FL	*421.30 FL
6	1		*REAR BUMPER	Crumpled	489.10 FL	*489.10 FL
7	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	145.80 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT BEAM	Serviceable	423.10 FL	*- FL
9	1		*REAR BUMPER INNER SPONGE	Serviceable	109.90 FL	*- FL
10	1		*REAR BUMPER LOWER GARNISH	Serviceable	230.70 FL	*- FL
11	1		*REAR BOOT LID LOGO EMBLEM	Necessary	50.00 FS	*50.00 FS
12	1		*REAR BOOT LID HYUNDAI EMBLEM	Necessary	50.00 FS	*50.00 FS
13	1		*REAR BOOT LID ELANTRA EMBLEM	Necessary	50.00 FS	*50.00 FS
14	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	150.00 FS	*150.00 FS
15	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,830.90</b>	<b>1,374.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	700.18	208.98
<b>Total Parts (\$\$)</b>	<b>3,130.72</b>	<b>1,165.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	400.00
2	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >