

AIG

Vehicle number	SKS6999Z
Make / Model	MERCEDES/CLA180
Chassis number	WDD1173422N171529
Accident date	26/12/20
Reference	2012-52

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	REAR BUMPER <i>distorted</i>	1509.95	✓
1	REAR BUMPER LOWER GARNISH <i>Crack</i>	563.50	✓
1	REAR BUMPER LOWER TRIM <i>bst</i>	304.80	✓
2	REAR BUMPER SIDE RETAINER <i>SVL</i>	79.20	X
2	REAR BUMPER SIDE BRACKET <i>HW</i>	222.20	X
1	REAR BUMPER REINFORCMENT <i>2 HW</i>	807.60	X
1	REAR BUMPER INNER BRACKET <i>HW 2 HW</i>	121.20	2 X
1	REAR BUMPER LOWER BRACKET <i>2 HW</i>	103.50	2 X
1	REAR BUMPER WIRE HARNESS <i>HW</i>	249.60	X
2	TAILLAMP <i>HW</i>	2160.00	X
2	TAILLAMP SEAL <i>HW</i>	74.40	X
4	PDC SENSOR <i>Dam</i> 312.00 x 4	1545.60	✓
1	END PANEL <i>HW</i>	1353.60	X
1	END PANEL TOP GARNISH <i>HW</i>	322.80	X
1	BOOTLID <i>bst</i>	2512.80	✓
1	BOOTLID LOCK <i>SVL</i>	369.15	X
1	BOOTLID PUSH BUTTOM <i>HW</i>	144.00	X
1	BOOTLID MERCEDES STAR LOGO <i>HW</i>	64.80	✓
1	BOOTLID EMBLEM CLA 180 <i>HW</i>	118.80	✓
1	BOOTLID WEATHERSTRIP <i>HW</i>	220.80	X
1	FRONT BUMPER <i>Crack</i>	1861.20	✓
2	FRONT BUMPER RETAINER <i>HW</i>	91.20	X
1	FRONT BUMPER INNER GUIDE <i>Crack</i>	234.00	✓
1	FRONT BUMPER REINFORCEMENT <i>2 HW</i>	445.20	2 ✓
1	FRONT BUMPER LOWER GRILLE <i>SVL</i>	207.60	X
1	FRONT BUMPER SPONGE <i>2 torn</i>	210.00	2 ✓
4	FRONT PDC SENSOR <i>Dam</i>	1527.20	✓
1	SENSOR WIRE HARNESS <i>HW</i>	457.20	X
1	FRONT NOZZLE <i>HW</i>	241.50	X
1	FRONT NOZZLE COVER <i>HW</i>	82.80	X
2	FRONT HEADLAMP <i>o/s Crack H/S HW Monday Crack</i>	6607.90	2 ✓
2	FRONT HEADLAMP BRACKET <i>o/s 2 HW H/S HW</i>	146.40	X
1	FRONT GRILLE <i>2 broken</i>	871.70	2 ✓
1	FRONT GRILLE EMBLEM LOGO <i>dislodged / broken</i>	174.80	✓
2	FRONT GRILLE EMBLEM CHROME GARNISH <i>2 Crack</i>	219.65	2 ✓
		1248.00	
		1875.00	
		87.00	
		1421.90	
		5746.00	
		692.00	

1	FRONT SUPPORT PANEL broken	918.50 ✓
1	FRONT SUPPORT PANEL TOP GARNISH HN	251.30 X
1	BONNET 131	1961.90 ✓
1	BONNET LOCK SVL	136.00 X
1	BONNET LOCK CATCH SVL	52.00 X
2	BONNET HINGE HN	186.60 X
		29732.95
Less 10 %		2998.49
Subtotal		26986.46
Balance C/F		26986.46
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR BUMPER CLIP HN	30.00 20/-
1	END PANEL TOP GARNISH CLIP HN	40.00 X
1	FRONT BUMPER CLIP HN	30.00 20/-
1	FRONT GRILLE CLIP HN	40.00 20/-
1	FRONT NUMBER PLATE 131	60.00 35/-
1	FRONT NUMBER PLATE GARNISH deformed	80.00 ✓
Subtotal		280.00
Balance C/F		27266.46
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	150.00 120/-
3	REMOVE AND RENEW REAR SENSOR	150.00 40/-
4	REMOVE AND RENEW FRONT SENSOR	150.00 40/-
5	REMOVE AND RENEW REAR EXHAUST	200.00 HN
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60/-
7	TRANSFER PARTS, ATTACHMENT FROM OLD BONNET TO NEW	200.00 HN
8	PANEL BEATING ON AFFECTED AREAS	2200.00 1000/-
9	SPRAY PAINTING ON AFFECTED AREAS	2200.00 1000/-
10	APPLY ANT RUST ON AFFECTED AREAS	120.00 40/-
Subtotal		5630.00
Grand total		32896.46

1565.00

175.00

2330.00

30/12/2020 @ 1500w

NA Antenna

4/Summer

6 days.

Nyan

Check PA prices.

Check MV

19431.57

Supp

1277.94

20709.57

L/S 16500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H

REPAIR PERFORMA INVOICE

AIG

Vehicle number	SKS6999Z
Make / Model	MERCEDES/CLA180
Chassis number	WDD1173422N171529
Accident date	26/12/20
Reference	2012-52

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	AIR CON CONDENSER <i>Painted</i>	1389.60 <i>1091.00</i>
1	FRONT RH HEADLAMP CONTROL UNIT <i>Svc</i>	1052.40 <i>X</i>
1	FRONT RH HEADLAMP XENON CONTROL UNIT <i>Svc</i>	480.40 <i>X</i>
1	FRONT BUMPER REINFORCMENT <i>repaired</i>	412.80 <i>X</i>
1	FRONT BUMPER REINFORCMENT BRACKET RH <i>1st</i>	195.60 <i>195.60</i>
	<i>1286.60</i>	3530.80
	<i>1157.40 94</i>	Less 10 % 353.08
		Subtotal 3177.72
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
S/No		
1	REMOVE AND REFIT CONDENSER AND TOP UP GAS	200.00 <i>120.00</i>
		Subtotal 200.00
		Grand total 3377.72

1277.40
1277.94