

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKU 388IM
 at Workshop m/s Nineteen
 of _____
 Insured: SLB177X
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$47k.
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

586A

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKU 388IM Yr Regn: 23/7/15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda vezel c.c 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp.Reading: 89504 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU1 1021228
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 215/60R16
 BS: DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 30/1/20 D.O.I. 31/1/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

11/1/21 LYA \$36005 rep 9k.
1/3 \$4500 confirmed with Jeremy

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

1) _____
 Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	



Mani Jasper
Not Authorized
hkh
d/s 4 HSDO
S-days

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
 Bartley Biz Centre, Singapore 417807
 Tel: (65) 9270 5882
 nineteenautowerks@gmail.com

Date : 31-Dec-20

Registration no. : SKU3881M / Honda Vezel 1.5X A

DOA : 30-Dec-20

Estmate No. : 19A027_SKU3881M_VEZEL

S/N	Qty	Item	Amount
LIST ITEMS			
1	1	Tailgate <i>Body 20</i>	1620.00 <i>95-3</i> ✓
2	1	Tailgate logo <i>11</i>	82.00 X
3	1	Tailgate emblem VEZEL <i>All</i>	86.20 <i>58.20</i> ✓
4	1	Tailgate outer garnish <i>11</i>	312.00 X
5	2	Tailgate reflector @ \$325.00 <i>11</i>	650.00 X
6	1	Tailgate wiper motor <i>11</i>	398.00 X
7	2	Tailgate windscreen moulding @ \$82.00 <i>All</i>	164.00 <i>88.20</i> ✓
8	1	Tailgate inner lock <i>11</i>	287.00 <i>109.20</i> ✓
9	1	Tailgate lock solenoid switch <i>11</i>	220.00 X
10	1	Tailgate lock striker <i>11</i>	97.00 X
11	1	Tailgate trimboard <i>del/em</i>	395.00 <i>175.50</i> ✓
12	1	Tailgate weatherstrip <i>11</i>	247.00 <i>101.30</i> ✓
13	2	Taillamp @ \$689.00 <i>M/s cnc</i>	1378.00 <i>460.80</i> <i>IPC</i>
14	1	Rear bumper <i>20</i>	985.00 <i>549.20</i> ✓
15	2	Rear bumper side retainer @ \$82.00 <i>11</i>	164.00 X
16	2	Rear bumper side garnish @ \$316.00 <i>11</i>	632.00 X
17	2	Rear bumper reflector @ \$117.00 <i>11</i>	234.00 X
18	1	Rear bumper lower cover <i>del/11</i>	326.00 <i>315.20</i> ✓
19	1	Smart buzzer <i>11</i>	224.00 X
20	1	Rear end panel <i>20/3uc</i>	785.00 <i>514.00</i> ✓
21	1	Rear end panel top garnish <i>11</i>	274.00 <i>188.00</i> ✓
22	1	Spare tyre panel <i>11</i>	1230.00 X
23	1	Spare tyre panel top board <i>11</i>	420.00 X
24	1	Spare tyre panel tools tray <i>11</i>	264.00 X
25	1	Exhaust pipe <i>11</i>	855.00 X
26	3	Exhaust mounting @ \$56.40 <i>11</i>	169.20 X
27	2	Rear fender arch garnish @ \$215.00 <i>Torn</i>	430.00 <i>180.20 x 2 = 360.40</i> ✓
28	2	Rear fender inner shield @ \$126.00 <i>11</i>	252.00 X
29	2	Rear fender inner garnish @ \$328.00 <i>11</i>	656.00 X
			13836.40
Less 20%			2767.28
			11069.12

23871
207
3096.80



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

Date : 31-Dec-20

Registration no. : SKU3881M / Honda Vezel 1.5X A

DOA : 30-Dec-20

Estmate No. : 19A027_SKU3881M_VEZEL

S/N	Qty	Item	Amount	
SPECIAL NETT ITEMS				
1	1	Sundries		
2	1set	Tailgate outer garnish clips	60.00	X
3	2set	Tailgate reflector clips @ \$25.00	45.00	X
4	2	Tailgate reflector seal @ \$20.00	50.00	X
5	1set	Tailgate trimboard clips	40.00	X
6	1	Tailgate windscreen primer & cleaner	55.00	40
7	1	Tailgate windscreen inner seal	100.00	X
8	1	Tailgate windscreen sealant	80.00	30
9	1	Tailgate sealant	100.00	40
10	2set	Taillamp clips @ \$30.00	100.00	X
11	2	Taillamp seal @ \$25.00	60.00	X
12	1set	Rear bumper clips	50.00	X
13	1set	Rear bumper lower cover clips	80.00	45
14	1set	Rear end panel top garnish clips	60.00	X
15	1set	Rear bumper top chrome plate & panel top garnish	40.00	X
16	1	Rear bumper defuser	260.00	200
17	2	Rear bumper reflector chrome garnish @ \$105.00	380.00	X
18	1	Rear end panel sealant	210.00	X
19	2set	Rear fender arch garnish @ \$45.00	80.00	50
20	2set	Rear fender inner shield @ \$30.00	90.00	X
21	2set	Rear fender inner garnish @ \$50.00	60.00	X
22	1	Reverse camera	100.00	X
23	1set	Reverse sensor with module	420.00	X
			300.00	200
			2820.00	
		Parts Total	13889.12	605

LABOUR & MISC CHARGES				
1	1	Panel beating and strenghten parts on accident area.	1800.00	680
2	1	Check wiring system after disconnect and connect.	80.00	20
3	1	R&R interior upholstery.	200.00	80
4	1	R&R tailgate component.	100.00	60
5	1	R&R tailgate windscreen.	180.00	120
6	1	R&R exhaust pipe.	200.00	X
7	1	R&R reverse sensor and check	100.00	50
8	1	To apply undercoating for rust roofing.	200.00	60
9	1	Spray painting on accident area.	1500.00	900
		Labour Total	4360.00	

Total Parts and Labour Cost of Repair 18249.12 1970