

CS/AGI 20014801 / Qvd3

## : TOTAL



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

## Estimation

Date:

30/12/2020

Vehicle:

SKN8110J

Make / Model:

MERCEDES C180

Chassis:

| No. | Description                                                | Unit      | Unit Price   | Amount              |
|-----|------------------------------------------------------------|-----------|--------------|---------------------|
|     | Parts Replacement:                                         |           |              |                     |
| 1   | BOOTLID / <i>hd</i>                                        | 1         | \$ 2,170.00  | \$ 2,170.00         |
| 2   | BOOTLID WEATHERSTRIP <i>X</i>                              | 1         | \$ 245.00    | \$ 245.00           |
| 3   | BOOTLID LOGO <i>X</i> / <i>Nec</i>                         | 1         | \$ 68.00     | \$ 68.00            |
| 4   | BOOTLID EMBLEM 'CLA180' <i>X</i> / <i>Nec</i>              | 1         | \$ 87.00     | \$ 87.00            |
| 5   | BOOTLID TOP LOCK / <i>Jan</i>                              | 1         | \$ 351.00    | \$ 351.00           |
| 6   | BOOTLID LOWER LOCK <i>X</i>                                | 1         | \$ 53.00     | \$ 53.00            |
| 7   | REAR BUMPER / <i>CR4</i>                                   | 1         | \$ 1,610.00  | \$ 1,610.00         |
| 8   | REAR BUMPER LOWER / <i>CR4</i>                             | 1         | \$ 712.00    | \$ 712.00           |
| 9   | REAR BUMPER CENTRE CHROME / <i>CR4</i>                     | 1         | \$ 398.00    | \$ 398.00           |
| 10  | REAR BUMPER SIDE BRACKET <i>X</i> <i>RH/CR4</i> <i>1/2</i> | 1         | \$ 159.00    | \$ 318.00           |
| 11  | REAR BUMPER CENTRE BRACKET / <i>CR4</i>                    | 1         | \$ 298.00    | \$ 298.00           |
| 12  | REAR BUMPER CENTRE TOP GARNISH <i>X</i>                    | 1         | \$ 159.00    | \$ 159.00           |
| 13  | REAR BUMPER REINFORCEMENT / <i>BT</i>                      | 1         | \$ 878.00    | \$ 878.00           |
| 14  | REAR BUMPER REINFORCEMENT BRACKET <i>X</i>                 | 2         | \$ 159.00    | \$ 318.00           |
| 15  | REAR BUMPER TOWING COVER <i>X</i>                          | 1         | \$ 79.00     | \$ 79.00            |
| 16  | REAR BUMPER SPONGE <i>X</i>                                | 1         | \$ 298.00    | \$ 298.00           |
| 17  | REAR BUMPER SENSOR / <i>short</i>                          | <i>24</i> | \$ 312.00    | \$ 1,248.00         |
| 18  | REAR BUMPER UNDERCOVER / <i>CR4</i>                        | 1         | \$ 384.00    | \$ 384.00           |
| 19  | REAR FENDER COWLING <i>X</i>                               | 2         | \$ 212.00    | \$ 424.00           |
| 20  | TAILAMP <i>RH/SCR</i> <i>1/2</i>                           | <i>12</i> | \$ 921.00    | \$ 1,842.00         |
| 21  | TAILAMP SIDE GARNISH <i>X</i>                              | 2         | \$ 68.00     | \$ 136.00           |
| 22  | REAR END PANEL <i>X</i> <i>R</i>                           | 1         | \$ 1,240.00  | \$ 1,240.00         |
| 23  | REAR END PANEL TOP GARNISH <i>X</i>                        | 1         | \$ 298.00    | \$ 298.00           |
| 24  | REAR FLOOR TOP BOARD <i>X</i>                              | 1         | \$ 321.00    | \$ 321.00           |
| 25  | EXHAUST SILENCER <i>X</i>                                  | 1         | \$ 1,874.00  | \$ 1,874.00         |
| 26  | EXHAUST CHROME <i>RH/SCR</i> <i>1/2</i>                    | <i>12</i> | \$ 398.00    | \$ 796.00           |
|     |                                                            |           |              | \$ 16,605.00        |
|     |                                                            |           | Less 10%     | \$ 1,660.50         |
|     |                                                            |           | <b>Total</b> | <b>\$ 14,944.50</b> |
|     | S/Nett items:                                              |           |              |                     |
| 1   | REAR BUMPER CLIPS SET                                      | 1         | \$ 50.00     | \$ 50.00            |
| 2   | REAR NUMBER PLATE C/W GARNISH                              | 1         | \$ 100.00    | \$ 100.00           |
| 3   | REAR END PANEL SEALANT                                     | 1         | \$ 80.00     | \$ 80.00            |
| 4   | REAR END PANEL CLIP                                        | 1         | \$ 30.00     | \$ 30.00            |
| 5   | BOOTLID SEALANT                                            | 1         | \$ 100.00    | \$ 100.00           |
| 6   | BOOTLID INNER TRIM CLIP SET                                | 1         | \$ 50.00     | \$ 50.00            |
|     |                                                            |           |              |                     |
|     |                                                            |           |              | \$ 410.00           |
|     | Labour to:                                                 |           |              |                     |

30  
X  
X  
X  
X  
X

|   |                                        |   |                          |             |              |
|---|----------------------------------------|---|--------------------------|-------------|--------------|
| 1 | SPRAY PAINTING ON AFFECTED AREAS       | 1 | \$ 1,000.00              | \$ 1,000.00 | 600          |
| 2 | PANEL BEATING ON AFFECTED AREAS        | 1 | \$ 1,000.00              | \$ 1,000.00 | 700          |
| 3 | TO CHECK ELECTRICAL WIRING             | 1 | \$ 120.00                | \$ 120.00   | 30           |
| 4 | TO REMOVE AND REFIT REAR BUMPER SENSOR | 1 | \$ 150.00                | \$ 150.00   | 40           |
| 5 | CHECK AND RESET FAULT CODE LIGHT ON    | 1 | \$ 250.00                | \$ 250.00   | 50           |
| 6 | TO RESPRAY UNDERCOATING                | 1 | \$ 150.00                | \$ 150.00   | 40           |
| 7 | APPLY ANTI RUST ON AFFECTED AREAS      | 1 | \$ 200.00                | \$ 200.00   | 40           |
|   |                                        |   |                          | \$ 2,870.00 |              |
|   |                                        |   |                          |             |              |
|   |                                        |   |                          |             |              |
|   |                                        |   | Parts Replacement Amount |             | \$ 15,354.50 |
|   |                                        |   | Total Amount for Labour  |             | \$ 2,870.00  |
|   |                                        |   | Total Amount             |             | \$ 18,224.50 |

Repair dy - 5 days

L/S

After pam photo

Sum Pin CLKy

31/12/2020

TP with the repairer

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: