



Pte Ltd

AIG INSURANCE

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PROFORMA INVOICE

Vehicle number	GBD3464E
Make / Model	NISSAN/CABSTAR
Chassis number	JN1SC2F24Z0856572
Accident date	17/12/20
Reference	2012-34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEM</u>		
1	TAILGATE	1941.66 bt
3	TAILGATE LOWER HINGE	138.00 bt
2	TAILGATE STOPPER	29.28 mis
1	TAILGATE SIDE HINGE LH	183.60 X
1	TAILGATE SIDE HINGE RH	183.60 X
1	TAILGATE LOCK CATCHER RH	57.00 X
1	TAILGATE LOCK CATCHER LH	57.00 X
1	FLOOR PANEL MEMBER	740.25 RP
1	TAILLAMP LH	291.40 RP
1	TAILLAMP RH	291.40 RP
1	TAILGATE PANEL RH	109.54 bt
1	TAILGATE PANEL LH	109.54 bt
1	SPARE TYRE TOP MEMBER	629.75 RP
1	REAR NUMBER PLATE LAMP	64.00 X nn
1	SIDE GATE LH	1860.14 RP
1	REAR VIEW MIRROR	489.50 X nn
Less 10%		7175.66
		717.57
		6458.09
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		6458.09
1	STEP GARNISH (AFTER MARKET)	450.00 bt
1	STICKER - NISSAN	70.00 mis
1	STICKER - 70km/hr	50.00 mis
1	REAR NUMBER PLATE	80.00 bt 30
1 SET	REVERSE SENSOR	400.00 mis 200
1	ALUMINIUM TAILGATE BOARD	1000.00 X nn
1	CANOPY	2800.00 X nn
Subtotal		4850.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		11308.09
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	80.00 30
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
3	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60
4	TRANSFER PARTS, ATTACHMENT FROM OLD SIDE GATE TO NEW	200.00 X
5	REMOVE AND REPLACE ALUMINIUM TAILGATE BOARD	400.00 X nn
6	REMOVE AND REPLACE CANOPY TO FACILITATE REPAIR	500.00 X
7	PANEL BEATING ON AFFECTED AREAS	1800.00 700
8	SPRAY PAINTING ON AFFECTED AREAS	1600.00 600
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		5080.00
Grand total		16388.09

Taufik 97495749
wp 12/1/12 esp
1/3 Resurvey after repair
Taufik E/khantawon

5 days
4208.37
4583350
5 days

2619.74
630
1450
4699.74
- 20%
3759.79
~ 3750