

Tiong Chun Motor Service

Blk 1 #01-135, Sin Ming Industrial Estate, Sector C

Singapore 575636. Tel: 6453-0895 HP: 9748 5436

Reg. No: 52827803K

Estimate Cost of repair to Nissan NV 200

To: India International Insurance Pte Ltd, Motor Claims Department

Vehicle No.: GBG 2366 X

Chassis No.: VSKYBAM20Z0145133

Policy No.: D20MCV0003388

To Supply:

1) 2pc Front Right + Left Hand Hood Lamp Assembly @ \$446.40	\$892.80
2) 1pc Front Left Hand Headlamp Lower Garnish	\$362.20
3) 1pc Front Bumper	\$655.20
4) 1pc Front Bumper Left Hand Fog Lamp	\$323.70
5) 1pc Front Bumper Reinforcement	\$614.90
6) 1pc Front Bumper Sponge	\$320.80
7) 1pc Front Left Hand Bumper Bracket	\$102.00
8) 1pc Front Left Hand Bumper Side Retainer	\$28.10
9) 1pc Front Left Hand Fender	\$504.70
10) 1pc Front Left Hand Fender Bottom Shield	\$135.20
11) 1pc Front Left Hand Door Side Mirror	\$351.80
12) 1pc Front Radiator Grille	\$338.00
13) 20 Pieces Clips (Per piece \$2.50)	\$550.00
Sub Total:	\$4679.40
Less discount 10%	\$4211.46

Job description

1) Labour to knock & straighten front support panel, etc, remove the damaged parts, replace with new parts.	\$800.00
2) To patty and spray painting.	\$500.00
3) To check wiring and align headlamp.	\$40.00
Sub Total:	\$1340.00

For all affected vehicle parts and labour cost to repair lump sum charge by us estimated:

\$5551.46