

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014809/R1GA3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0006396
Claimant Vehicle No :	SKB3313L	Insured Vehicle No :	SKV53B
Date of Loss:	11/12/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0002716

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB3313L	Engine No:	015351001538204PT
Make & Model:	JAGUAR XE, 2.0 I4P TSS (A)	Chassis No:	SAJAB4AG0HA972285
Reg. Date:	30/03/2017 (Man. Year: 2016)	Odometer:	68986 km
Colour:	Blue		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35Z R19	Rear Tyre Size:	225/35Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,948.10	2,584.62	4,363.48	62.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,125.00	4,425.00	1,700.00	27.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,073.10	7,009.62	6,063.48	46.38
+ GST 7.00/7.00% (\$\$)	915.12	490.67	424.45	46.38
Nett Amount (\$\$)	13,988.22	7,500.29	6,487.93	46.38
+ Car Rental (4.0 x S\$130.00/day + 7.00% GST) (\$\$)		556.40		
Nett Liability (\$\$)		8,056.69		

INSPECTION

Date of Assignment:	31/12/2020		
Date Inspected:	25/01/2021	Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee 2) 45 Leng Kee Road Singapore 159103
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

4/12/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	143	JAGUAR XE 2.0 I4P TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB3313L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL -VALANCE	Cut	605.90 FS	*545.31 FS
2	1		*JT4N7762LML/COVER -BU	Repair	1,068.20 FS	*- FS
3	1		*MOUNTING -BRACKET RH	Serviceable	115.80 FS	*- FS
4	1		*MOUNTING -BRACKET LH	Serviceable	115.80 FS	*- FS
5	1		*MOUNTING -BRACKET CTR	Serviceable	97.20 FS	*- FS
6	1		*BUMPER BEAM REAR XE	Serviceable	607.30 FS	*- FS
7	1		*TRUNK LIP XE	Bent	1,479.60 FS	*1,331.64 FS
8	1		*JT4N7585/BADGE REAR	Necessary	109.00 FS	*98.10 FS
9	1		*JT4N7586/BADGE	Necessary	199.60 FS	*179.64 FS
10	1		*BADGE REAR 20T XE	Necessary	130.50 FS	*117.45 FS
11	1		*REAR LAMP FOG RH XE	Serviceable	347.20 FS	*- FS
12	1		*FOG LAMP REAR LH XE	Cracked	347.20 FS	*312.48 FS
13	1		*BODY PANEL SEALANT X	Not Necessary	955.20 FS	*- FS
14	1		*ADHESIVE SEALER FL2	Not Necessary	709.60 FS	*- FS
15	1		*NUMBER PLATE & HOLDER	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,948.10	2,584.62
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BOOTLID ,REAR BUMPER ,VALANCE BOOTLAMP	New	2,700.00	1,800.00
2	TO SPRAYPAINT ON REAR BUMPER ,BOOTLID	New	2,400.00	1,600.00
3	TO REMOVE ,REFIT & TRANSFER REAR BOOTLID PARTS	New	500.00	500.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00
Gross Labour Cost (\$\$)			6,125.00	4,425.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >