


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



SERVICE ESTIMATE

89155 - C00001 SL: SERVICE SALES - PC
Mr Willy Tjahyadi Iwan
68 Toh Tuck Road
#04-01
Singapore
Singapore 596733

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date : 14/12/2020
WIP No. : 55020
Veh.In/Out:

*Tel.No. : Mobile: 82981688

Reg.No. : SKB3313L

Reg.date : 30/03/2017

Mileage : 0

Chassis No: SAJAB4AG0HA972285

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Willy Tjahyadi Iw

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOTLID, <i>cfw</i>	0	2700.00	0		2,700.00 S 1800 /	
	REAR BUMPER, VALANCE, BOOTLAMP						
800	TO SPRAYPAINT ON REAR BUMPER, <i>cfw</i>	0	2400.00	0		2,400.00 S 1600 /	
	BOOTLID						
802	TO REMOVE, REFIT & TRANSFER	0	500.00	0		500.00 S /	
	REAR BOOTLID PARTS						
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00 S Xnn	
280	TO CHECK WIRING INCLUDE	0	525.00	0		525.00 S /	
	RESETTING OF ALL ELECTRICAL MODULES						

PANEL-VALANCE *cfw*
JT4N7762LML/COVER-BU *repair*
MOUNTING-BRACKET RH ? *xsul*
MOUNTING-BRACKET LH ? *xsul*
MOUNTING-BRACKET CTR ? *xsul*
BUMPER BEAM REAR XE ? *xsul*

1.0 EA 605.90 605.90 S 545.31
1.0 EA 1068.20 1,068.20 S
1.0 EA 115.80 115.80 S
1.0 EA 115.80 115.80 S
1.0 EA 97.20 97.20 S
1.0 EA 607.30 607.30 S

Sub Total 13,073.10

Net 13,073.10

GST @ 7.00 915.12

Total 13,988.20

Paid 0.00

Please Pay 13,988.20

Prepared: 11-Dec-2020; 11-Dec-2020

SINGAPORE ACCIDENT STATEMENT

DISCLAIMER NOTICE
 Please report accurately the details of the accident to speed up the claims process.
 This form is not intended to be used as evidence in any court of law. Any false information or withholding of material facts may affect the insurance company's liability.
 The insurance company is not responsible for any loss or damage to the vehicle or its contents. Any loss or damage to the vehicle or its contents may affect the insurance company's liability.

SERVICE ESTIMATE

89155 - C00001 SL: SERVICE SALES - PC

Mr Willy Tjahyadi Iwan

68 Toh Tuck Road

#04-01

Singapore

Singapore 596733

Exact Location of Accident

Additional Location Information

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Willy Tjahyadi Iw

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 14/12/2020

WIP No. : 55020

Veh.In/Out:

*Tel.No. : Mobile: 82981688

Reg.No. : SKB3313L

Reg.date. : 30/03/2017

Mileage : 0

Chassis No: SAJAB4AG0HA972285

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

TRUNK LIP XE	1.0 EA	1479.60				1,479.60 S	1331.64
JT4N7585/BADGE REAR	1.0 EA	109.00				109.00 S	98.10
JT4N7586/BADGE	1.0 EA	199.60				199.60 S	179.64
BADGE REAR "20t" XE	1.0 EA	130.50				130.50 S	117.45
REAR LAMP FOG RH XE	1.0 EA	347.20				347.20 S	
FOG LAMP REAR LH XE	1.0 EA	347.20				347.20 S	312.48
BODY PANEL SEALANT X	1.0 EA	955.20				955.20 S	
ADHESIVE SEALER FL2	1.0 EA	709.60				709.60 S	

Passer
 4p 90000068
 4 days
 28/01/2021 P1150
 Ready before part

Gross Total. 13,073.10

Net..... 13,073.10

GST @ 7.0% 915.12

Total..... 13,988.20

Paid..... 0.00

Please Pay.. 13,988.20

Labour Total 6,185.00
 Parts Total 6,888.10
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated