



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/1010/2020/GW
DATE	:	28-Dec-20
WIP	:	64045

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO :XD 4524 Z

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

OWNER'S NAME	:	YAN SAN METALS PTE LTD
ADDRESS	:	BLK 99 BEDOK NORTH AVE 4 #20-1904 SINGAPORE 460099
TELEPHONE	:	HP +65 92778807
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	A300297824MCY
VEHICLE NO	:	SKS 7273 C
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	30/4/2015
ENGINE NO	:	CZC 244190
CHASSIS NO	:	WAUZZZ8V6F1115526
MILEAGE	:	
DATE IN	:	22-Dec-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	22-Dec-20
PLACE OF ACCIDENT	:	19 PIONEER RD, SINGAPORE 628499

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 7273 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00 ✓	
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 1400	
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00 1500	
4	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00 ✓	
5	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILLIATE FENDER RENEWAL.	S/N \$ 600.00 ✓	
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00 ✓ invoice?	
SUB - TOTAL LABOUR CHARGES		: <u>\$ 5,660.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 7273 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 /	
8	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 /	
9	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 /	
10	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 560.00 /	
11	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. CUT OUT AND WELD RHS REAR FENDER, RHS SILL PANEL, RHS B-PILLAR AND RHS A-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,800.00 / 5000 9100	
12	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS B-PILLAR, RHS A-PILLAR, RHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 7,950.00 7150	
SUB- TOTAL LABOUR CHARGES		: \$ 21,310.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 7273 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST WHEEL ALIGNMENT. TO RENEW RHS FRONT RIM AND RHS REAR RIM.	S/N \$ 560.00	report?
14	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 1,800.00	? photo
15	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	? photo
16	TO PUT VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	? photo
17	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	invoice?
18	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	9.1 / report? 192
TOTAL LABOUR CHARGES		: \$ 33,194.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>de/</i>		\$	1,847.00
2 REAR BUMPER FIXING PARTS <i>X NN</i>		\$	191.00
3 REAR BUMPER GUIDE SECTION - LH/RH <i>NNx ?</i>	2	\$	32.00
4 REAR BUMPER LOCKING MECHANISM <i>?</i>	2	\$	59.00
5 REAR BUMPER GUIDE SECTION - RH <i>X NN</i>		\$	66.00
6 REAR FENDER RH TO A-PILLAR <i>bt/</i>		\$	3,436.00
7 REAR WINDSCREEN <i>nee/ photo</i>		\$	805.00
8 1/4 GLASS - RH <i>nee/ photo</i>		\$	563.00
9 PRIMER <i>ne/</i>		\$	19.00
10 SILL TRIM STRIP - RH <i>?</i>		\$	69.00
11 SILL TRIM STRIP <i>?</i>		\$	125.00
12 WHEEL HOUSING LINER <i>?</i>		\$	237.00
13 WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>		\$	88.00
14 REAR DOOR - RH <i>bt/</i>		\$	2,494.00
15 REAR DOOR OUTER SEAL - RH <i>ne/</i>	NEC	\$	159.00
16 BONDING AGENT <i>ne/</i>	NEC	\$	47.00
17 CLEANING SOLUTION <i>ne/</i>	NEC	\$	65.00
18 APPLICATOR <i>ne/</i>		\$	7.00
19 REAR DOOR CATCH <i>ne/ photo</i>		\$	93.00
20 REAR DOOR SEAL INNER <i>ne/</i>		\$	189.00
SUB TOTAL SPARE PARTS	:	\$	10,591.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR DOOR HINGE - RH UPPER ?		\$ 77.00	
22	REAR DOOR HINGE HALF UPPER PART - RH ?		\$ 46.00	
23	LOWER FRONT DOOR HINGE HALF LOWER PART - RH ?		\$ 75.00	
24	EXTERIOR REAR DOOR HANDLE - RH ?		\$ 359.00	
25	DOOR HANDLE HOUSING - RH <i>sea</i> ✓		\$ 51.00	
26	REAR DOOR MOUNTING BAR - RH ?		\$ 156.00	
27	DOOR RELEASE CABLE ?		\$ 50.00	
28	WINDOW REGULATOR - RH ?		\$ 246.00	
29	DOOR WIRING SET ?		\$ 330.00	
30	WINDOW SLOT SEAL - RH REAR X NN		\$ 292.00	
31	C-PILLAR TRIM - RH <i>re</i> ✓		\$ 114.00	
32	B-PILLAR TRIM - RH <i>re</i> ✓		\$ 115.00	
33	FRONT DOOR - RH <i>lt</i> ✓		\$ 2,494.00	
34	FRONT DOOR OUTER SEAL - RH <i>re</i> ✓	NEC	\$ 159.00	
35	BONDING AGENT <i>re</i> ✓	NEC	\$ 47.00	
36	CLEANING SOLUTION <i>re</i> ✓	NEC	\$ 65.00	
37	FRONT DOOR ATTACHMENT PARTS ?		\$ 238.00	
38	FRONT DOOR CATCH <i>re</i> <i>photo</i>		\$ 104.00	
39	FRONT DOOR SEAL INNER <i>re</i> ✓		\$ 159.00	
40	FRONT DOOR HINGE - UPPER/LOWER ?	2	\$ 154.00	
SUB TOTAL SPARE PARTS		:	\$ 5,331.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 EXTERIOR FRONT DOOR HANDLE - RH ?		\$ 359.00	
42 FRONT DOOR HANDLE CAP - RH mis /		\$ 53.00	
43 FRONT DOOR SLIDE VALVE - RH ?		\$ 22.00	
44 FRONT DOOR LOCK CYLINDR - RH ?		\$ 517.00	
45 FRONT UNDERLAY - RIGHT FRONT/REAR ?	2	\$ 11.00	
46 FRONT DOOR MOUNTING BAR - RH ?		\$ 155.00	
47 FRONT DOOR RELEASE CABLE ?		\$ 50.00	
48 EXTERIOR MIRROR MOUNTING -- RH on /		\$ 1,013.00	
49 MIRROR CAP - RH on /		\$ 148.00	
50 MIRROR GLASS - RH on X NN		\$ 1,644.00	
51 CORNER TRIM - RH on /		\$ 45.00	
52 WINDOW GUIDE TRIM STRIP - RH ?		\$ 254.00	
53 B-PILLAR TRIM - RH on /		\$ 103.00	
54 WINDOW SLOT SEAL - RH FRONT on 50 /		\$ 305.00	
55 WINDOW REGULATOR - RH ?		\$ 261.00	
56 FRONT DOOR PANEL TRIM COVER ? X NN		\$ 13.00	
57 FRONT DOOR WIRING SET ?		\$ 571.00	
58 TYRE PRESSURE DATA PLATE on /		\$ 28.00	
59 DATA TAG on /		\$ 457.00	
60 FRONT FENDER - RH on /		\$ 841.00	
SUB TOTAL SPARE PARTS	:	\$ 6,850.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 FRONT FENDER ATTACHMENT PARTS ?		\$ 71.00	
62 FRONT FENDER BRACKET - RH X NN		\$ 38.00	
63 FRONT FENDER BRACKET - RH X NN		\$ 27.00	
64 FRONT FENDER BRACKET - RH X NN		\$ 27.00	
65 FRONT FENDER BRACE - RH ?		\$ 95.00	
66 FRONT FENDER CLOSING ELEMENT - RH X NN		\$ 33.00	
67 FRONT FENDER INSULATION - RH X NN		\$ 42.00	
68 WHEEL HOUSING LINER - RH ?		\$ 167.00	
69 WHEEL HOUSING LINER ATTACHMENT PARTS ?		\$ 88.00	
70 FRONT BUMPER de/		\$ 1,987.00	
71 FRONT BUMPER FIXING PARTS ?		\$ 185.00	
72 FRONT BUMPER GUIDE SECTION - RH ?		\$ 38.00	
73 FRONT BUMPER AIR GUIDE GRILLE - RH X NN		\$ 108.00	
74 FRONT ALUMINIUM RIM - RH 8cm	2	\$ 1,397.00	
75 FRONT TRACK CONTROL ARM - RH LOWER ?		\$ 363.00	
76 FRONT WHEEL BEARING HOUSING ?		\$ 563.00	
77 FRONT WHEEL BEARING ?		\$ 485.00	
78 FRONT GAS SHOCK ABSORBER ?		\$ 259.00	
79 FRONT GUIDE JOINT - RH ?		\$ 120.00	
80 REAR WINDSCREEN SEALANT m/	S/N	\$ 200.00	
SUB - TOTAL SPARE PARTS	:	\$ 6,293.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
81 1/4 GLASS SEALANT <i>me</i> ✓	S/N	\$ 100.00	
82 METAL FILLER POWDER <i>me</i> ✓	S/N	\$ 280.00	
83 STONE CHIP <i>me</i> ✓	S/N	\$ 180.00	
84 CAVITY WAX <i>me</i> ✓	S/N	\$ 140.00	
85 ACRYLIC SEALANT <i>me</i> ✓	S/N	\$ 180.00	
86 SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS	:	\$ 30,445.00	
TOTAL LABOUR CHARGES	:	\$ 33,194.00	
GRAND TOTAL	:	\$ 63,639.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasu - HP 90010068

: 31/12/2020 @ 1210

: 25 days

: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT