

L OINEAR BIMIDED ...

AP AUTOMOTIVE SERVICES PTE LTD ROC: 202022890H BLOCK 9006 TAMPINES STREET 93 #01-202 SINGAPORE 528840 TEL: 6784 4465 FAX: 6787 4886

Estimation

Date

Vehicle

SFP 2040 R

Make/Model

MITSUBISHI EVO 10

Chassis No.

CZ4A0000909

No.	Description		Unit	Unit Price	Amount	1
	Parts Replacment					1
	HEADLAMP RH	coal	1		\$ 1123.60 -	1016
2	FRONT BUMPER	de	1		\$ 864.10 /1 -	
3	FRONT BUMPER RETAINER RH	de	1		\$31.50 / -	Ĩ
4	FRONT FENDER RH	bd	1		\$951.40 / -	888
5	FRONT FENDER GARNISH RH	de	1		\$ 97.80. / / -	
6	FRONT FENDER COWLING RH	tu	1		\$117.10.1 / -	1
7	FRONT FENDER INNER PANEL RH	RY	1		\$ 1512.40. XR -	1
8	FRONT DOOR PILLAR RH	61/RX	1		\$ 594.30.	394
. 9	FRONT DOOR RH	bi	1.		\$ 936.10-11	1
10	FRONT DOOR SIDE MIRROR ASSY RH	K	1		\$493.30 X ny -	
11	FRONT DOOR HANDLE RH	×	1		\$ 79.10, x un.	1
12	FRONT DOOR WINDOW STICKER RH	Wes-	1		\$ 29.40.	
13	FRONT DOOR WINDOW MOULDING WITH CHRON	MERH AL	1		\$ 129.60.	1
14	FRONT DOOR INNER WINDOW MOULDING RH	X	1	(1.7 	\$ NIL. XUN-	1
15	FRONT DOOR LOCK RH plus "	64	1		\$ 293:40.	1
16	FRONT DOOR LOCK CATCH RH	b*/	1		\$ 29.101	1
17	FRONT DOOR INNER BOARD RH	de 1	1		\$ 591.70.	4
18	FRONT DOOR WINDOW REGULATOR RH	13/	1		\$ 151.301	1
19	FRONT DOOR POWER WINDOW MOTOR RH	mik	1		\$ 437.10.	200
20	FRONT DOOR HINGE SET RH	15/	2	\$ 31.16	\$ 74.80.	327
21	FRONT DOOR CHECKER RH	12/	1	1 - 1 10	\$ 29.90.11	1 /
22	FRONT DOOR WEATHERSTRIP RH	nec	1		\$ 134.30.11	-
23	FRONT DOOR INNER WEATHERSTRIP RH	cell	1		\$ 179.40.	1
24	FRONT DOOR INNER STEP GARNISH RH	te	1		\$ 57.30.) ا
25	DOOR CENTER PILLAR RH	HX	1			1200
26	DOOR CENTER PILLAR INNER GARNISH TOP RH	X	1	**	\$ 499.30.V -	399
	DOOR CENTER PILLAR INNER GARNISH LOWER RH		1		\$ 107.30 Xun -	4
	EAR DOOR RH	h7/	1		\$ 136.40. Yun -	4
_	EAR DOOR WINDOW STICKER RH				\$859.30.	4
	EAR DOOR WINDOW MOULDING WITH CHROME	ne /	1		\$ 31.80. 1	_
31 R	EAR DOOR INNER WINDOW MOULDING RH		- 1		\$187.401	_
		*	1		\$ NIL. Xny -	
- 2	EAR DOOR LOCK RH	*	1	· · · · · · · · · · · · · · · · · · ·	\$ 294.10 XNN -	
-	EAR DOOR LOCK CATCH RH	X	, 1		\$ 29.40. Xun	
	AR DOOR INNER BOARD RH	ac	1		\$ 596.40 -	
	AR DOOR WINDOW REGULATOR RH	BH	1		\$181.40.	
	AR DOOR POWER WINDOW MOTOR RH	mx	1		\$ 449.40.10 -3	25
37 RE	AR DOOR HINGE SET RH Phops.	44	2	\$40-80	\$80.60 1	16_

Λ.

8952.50

138 F	REAR DOOR CHECKER RH	6+26	1		\$ 31.40.1 // -	
39 F	REAR DOOR WEATHERSTRIP RH	Nei	1		\$ 139.70 // -	_
40	REAR DOOR INNER WEATHERSTRIP RH	X	1		\$ 18810. * 44 -	
41	REAR DOOR INNER STEP GARNISH RH	K	1		\$ 60.70. × 44 -	
\rightarrow	ROCKER PANEL RH	RY	1		\$ 609. HD. X nn	_
43	ROCKER PANEL OUTER GARNISH RH	cry -	1		\$ 879.10.	_679
	REAR WINDSCREEN MOULDING	Pli	1		\$ 43.70.	
45	REAR FENDER RH	144/	1	i:	\$ 873.10.	_
_	REAR FENDER INNER PANEL RH	RY	1		5461.40 XR	_
	REAR FENDER COWLING RH	?	1	de		_
	REAR BUMPER	Ex	1	m/	\$ 732.90 / -	_
	REAR BUMPER RETAINER RH	7	1	DAM 🗸	\$ 21.70 -	
50	FRONT ABSORBER RH	?	1	51-	\$719.40.	4
51	FRONT LOWER ARM RH	7	1	ht-	\$ 596.10.	544
52	FRONT KNUCKLE ARM RH	7	1	4	\$ 497.30. 5 -	443
53	FRONT KNUCKLE BEARING RH	2	1	pt-	\$419.70.	_
54	FRONT BEARING HUB RH	×	1	61/	\$ 401.40. A X NV-	_
55	FRONT DRIVE SHAFT RH	×	1		\$1173.10 · Xun -	
56	REAR ABSORBER RH	á	1	41	\$173.40 / / -	_
57	REAR LOWER ARM RH		1	ht/	\$ 284.10. / -	
58	REAR KNUCKLE RH	(1	ht-	\$421.40.	1.11
÷59	REAR KNUCKLE BEARING RH	2	1	ht-	\$471.00 -	378
- 60	RAR BEARING HUB RH	7.	1	SVC X	\$ 479.30 VX -	_
63	REAR AXLE	X	1		\$ 1,204.10 Xun	1
62	FRONT DRIVER SEATBELT	'm/	1		\$ 639.40.	439
				Total	\$ 15505.10	
L_	\			Less 10%	\$ V -	
	, 11 6	P. #		Total	\$ 13954.59]

	S/Nett Items							1
1	HEADLAMP PROTECTIVE FILM	1		600	\$ ×	my.	600.00	1
2	FRONT BUMPER CLIPS SET	1		100	\$ 30	سر بسد	100.00	1
3	FRONT BUMPER LOWER CARBON FIBRE & this price	1	4800	6000	\$ eng	~	6,000.00	1
4	FRONT FENDER QUARTER GARNISH CARBON FIBRE * chich p	~U· 1	4100	800	\$ de-	/	800.00	1
5	FRONT DOOR PILLAR SEALANT	1		200	\$ ×	un	200.00	1
6	FRONT FENDER INNER PANEL SEALANT	1		200	\$ ×	24	200.00	1
7	FRONT FENDER SIGNAL LAMP of which pice.	1		500	\$ 7	Xnn	500.00	1
8	FRONT DOOR INNER BOARD CLIPS SET	1		100	\$ 200	4/	100.00	1
9	FRONT DOOR INNER ANTI SLIP MAT	1		400	\$?	Xun	400.00	1
10	DOOR CENTER PILLAR SEALANT	1		200	\$ 50.	سر بود	200.00	1
11	REAR DOOR INNER BOARD CLIPS SET	1		100	\$ 29.	41	100.00	١
12	REAR DOOR PROTECTOR STICKER	1		300	\$ cut-	100.	300.00	ı
13	REAR DOOR INNER ANTI SLIP MAT	1		400	\$ 7	XMY	400.00	ı
14	ROCKER PANEL SEALANT	1		250	\$ X	un	250.00	l
15	ROCKER PANEL OUTER GARNISH CLIPS SET	1		100	\$ 300	il	100.00	
16	ROCKER PANEL OUTER GARNISH PROTECTOR STICKER	1		200	\$	(los)	200.00	
17	REAR WINDSCREEN SEALANT	1		150	\$ 480		150.00	
18	REAR FENDER SEALANT	1		250	\$ 80	14/	250.00	
19	REAR FENDER INNER PANEL SEALANT	1		250	\$ ×	(NN	250.00	

			Total	\$	23,050.00
27	REAR RIM	1	4000	\$	64/500 4,000.00
26	REAR TYRE	1	A00. 800	\$ 4	n 70% 800.00
25	FRONT RIM	1	4000	\$	art/ 300 4,000.00
24	FRONT TYRE	1	800	\$	× 777 800.00
23	REAR BUMPER LOWER	1	2000	\$	Ry 2,000.00
22	REAR BUMPER CLIPS SET	1	100	\$	30 mg/ 100.00
21	REAR FENDER COWLING CLIPS SET	1	100	\$	20 k New 100.00
_	REAR FENDER PROTECTOR STICKER	1	150	\$	5t no 150.00

2590

	LABOUR			1		
1	SPRAY PAINT ON AFFECTED AREAS	1	2800	\$	Leco	2,800.00
2	PANEL BEATING ON AFFECTED AREAS	1	3200	\$	1600.	3,200.00
3	TO RNR REAR WINDSCREEN	1	400	\$	120	400.00
3	TO RNR PROTECTOR STICKER	1	200	\$	50	200.00
4	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$	第30.	150.00
5	TO RNR INNER TRIM AND UPHOISTERY	1	800	\$	100.	800.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$	80	250.00
7	TO RNR UNDERCARRIAGE	1	250	\$	150%	
8	TO CHECK WHEEL BALANCING	1	250	\$	60	250.00
	TO CHECK WATER LEAK	1	150	\$	N 50	
	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1 1	600	\$	1500	600.00
	TO PERFORM RUST PROOFING	1	600	\$	100	600.00
12	TO RNR REAR AND FRONT DOOR MECHANISM	1	800	\$	120.	800.00
ليد						
			otal Labour	\$	1	0.450.00

Total Labour 10,450.00 Parts Replacement Amount 23,050.00

> **Total Amount** 33,500.00

Taythi 97495749 WP 4/1/21@430 pm 2/5 Resury bythe paint 10deps

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

13954.59 21454.59 4517,150