




NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0051/12/20 Date : 22/12/2020

THIRD PARTY CLAIM

M/S : CHUAN MENG ELECTRICAL CONTRACTOR
9003 Tampines Street 93
#02-182 Singapore 528837

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLT8222B BMW 730LI
INSURED : CHUAN MENG ELECTRICAL CONTRACTOR ENGINE# :
DATE OF ACCIDENT : 19/12/2020 CHASSIS# :
POLICY NO : MA010371

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts				
1 front bumper side retainer RH	1@	28.40	28.40	28.40 <i>net</i>
2 front bumper parking sensor RH	1@	238.05	238.05	238.05 <i>net</i>
3 front bumper chrome RH	1@	48.95	48.95	48.95 <i>X NN</i>
4 front bumper	1@	1565.90	1565.90	1,565.90 <i>dev</i>
				<u>1,881.30</u>

Total Material

\$1,787.23

Labour & Misc

1 Remove and install front bumper, front headlamp, front fog lamp L & R, indicator lamp, front bumper chrome L & R, wiper nozzle cover, towing hook cover & parking sensor.	350.00 <i>250.</i>
2 Spray Painting	300.00 <i>250</i>
3 Renew parking sensor and setting.	80.00 <i>30</i>
4 Check Wiring system.	25.00 <i>✓</i>
	<u>755.00</u>

Total Labour

\$755.00

Nett Total Before Gst

\$2,542.23

Parts: \$1832.35

-5% = \$91.62

\$1740.73

Lab: \$555.00

\$2295.73

Tanpin 9749547 / 67418437

wp' 23/12/20 e 1245

4/3 Resurvey after repair

2 days

Tanpin 11111111

4/3 Sur: \$1800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: