

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000021/APA3Q2

Date: 12/04/2021

### REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070010887   |
| <b>Claimant Vehicle No :</b> | SKX7959G                             | <b>Insured Vehicle No :</b> | SMR9249S     |
| Date of Loss:                | 23/12/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1386241857SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKX7959G</b>                   | Engine No:  | CJE067992         |
| Make & Model:               | AUDI A4, 1.8 TFSI MU (EU6) (A)    | Chassis No: | WAUZZZ8KXEA058221 |
| Reg. Date:                  | 27/01/2014 (Man. Year: 2013)      | Odometer:   | 80218 km          |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1798 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 255/35 R19    | Rear Tyre Size:  | 255/35 R19    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                           | 12,363.10        | 2,898.00        | 9,465.10         | 76.56        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00             |              |
| Labour                                          | 1,650.00         | 580.00          | 1,070.00         | 64.85        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00             |              |
| Towing                                          | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>14,013.10</b> | <b>3,478.00</b> | <b>10,535.10</b> | <b>75.18</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>2,700.00</b> |                  |              |
| (S\$)                                           | 14,013.10        | 2,700.00        | 11,313.10        | 80.73        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 980.92           | 189.00          | 791.92           | 80.73        |
| <b>Nett Amount (S\$)</b>                        | <b>14,994.02</b> | <b>2,889.00</b> | <b>12,105.02</b> | <b>80.73</b> |
| <b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b> |                  | 320.00          |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 7.45            |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>3,216.45</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>3,200.00</b> |                  |              |

### INSPECTION

|                             |            |                                                                                                                  |
|-----------------------------|------------|------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 28/12/2020 |                                                                                                                  |
| Date Inspected:             | 28/12/2020 | Inspected At: New Zen Werkz Pte Ltd (HQ)<br>Blk 3 kaki Bukit road 1 #03-04 Eunost Technolink<br>Singapore 415935 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                                  |

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition            | Repairer's | Amount       |
|-----|-----|----------|------------------------------------|----------------------|------------|--------------|
| 1   | 1   |          | *REAR BOOT LID                     | Not Necessary        | 2,552.10 F | *- FL        |
| 2   | 2   |          | *REAR BOOT LID LAMP                | Not Necessary        | 1,310.00 F | *- FL        |
| 3   | 1   |          | *REAR BOOT LID EMBLE LOGO          | Not Necessary        | 82.00 F    | *- FL        |
| 4   | 1   |          | *REAR BOOT LID NUMBER PLATE        | Not Necessary        | 50.00 F    | *- FL        |
| 5   | 2   |          | *REAR BOOT LID NUMBER PLATE LAMP   | Not Necessary        | 90.00 F    | *- FL        |
| 6   | 1   |          | *REAR BOOT LID INNER LOCK          | Not Necessary        | 324.00 F   | *- FL        |
| 7   | 1   |          | *REAR BOOT LID INNER LOCK SWITCH   | Not Necessary        | 238.00 F   | *- FL        |
| 8   | 1   |          | *REAR BOOT LID INNER LOCK SENSOR   | Not Necessary        | 550.00 F   | *- FL        |
| 9   | 1   |          | *REAR BOOT LID INNER RUBBER        | Not Necessary        | 244.00 F   | *- FL        |
| 10  | 1   |          | *REAR BOOT LID TOWING COVER        | Not Necessary        | 88.00 F    | *- FL        |
| 11  | 2   |          | *REAR BOOT LID TAIL LAMP           | Not Necessary        | 1,492.00 F | *- FL        |
| 12  | 1   |          | *REAR BOOT LID A4 LOGO             | Not Necessary        | 59.00 F    | *- FL        |
| 13  | 1   |          | *REAR BOOT LID 1.8 LOGO            | Not Necessary        | 59.00 F    | *- FL        |
| 14  | 1   |          | *REAR BUMPER                       | Deformed             | 1,760.00 F | *1,760.00 FL |
| 15  | 4   |          | *REAR BUMPER REVERSE SENSOR        | Damaged (2 PCS ONLY) | 940.00 F   | *470.00 FL   |
| 16  | 2   |          | *REAR BUMPER SIDE BRACKET          | Cracked              | 250.00 F   | *250.00 FL   |
| 17  | 1   |          | *REAR BUMPER REINFORCEMENT         | Dented               | 710.00 F   | *710.00 FL   |
| 18  | 2   |          | *REAR BUMPER REINFORCEMENT BRACKET | Not Necessary        | 330.00 F   | *- FL        |
| 19  | 10  |          | *REAR BUMPER CLIPS                 | Necessary            | 60.00 F    | *30.00 FL    |
| 20  | 1   |          | *REAR END PANEL                    | Repair               | 890.00 F   | *- FL        |
| 21  | 1   |          | *REAR END PANEL TOP GARNISH        | Not Necessary        | 285.00 F   | *- FL        |

F=Franchise part. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>12,363.10</b> | <b>3,220.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | <b>0.00</b>      | <b>322.00</b>   |
| <b>Total Parts (\$\$)</b>                                 | <b>12,363.10</b> | <b>2,898.00</b> |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                       | Particulars                                   | Lab.Type | Repairer's | Amount |
|--------------------------|-----------------------------------------------|----------|------------|--------|
| <b>Labour Items</b>      |                                               |          |            |        |
| 1                        | TO REMOVE & REFIX FRONT & REAR REVERSE SENSOR | New      | 150.00     | 50.00  |
| 2                        | TO REMOVE & REFIX CUSHION                     | New      | 120.00     | 0.00   |
| 3                        | TO CHECK WIRING SYSTEM                        | New      | 60.00      | 30.00  |
| 4                        | TUFF KOTE                                     | New      | 120.00     | 0.00   |
| 5                        | PANEL BEATING                                 | New      | 600.00     | 250.00 |
| 6                        | SPRAY PAINTING                                | New      | 600.00     | 250.00 |
| Gross Labour Cost (\$\$) |                                               |          | 1,650.00   | 580.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >