

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

27th December 2020

SIVA DASS PRUSOTHAM SINGH

Blk 3 Kaki Bukit Road 1

03 – 04 Eunost Technolink

Singapore 415935

TPALG
Xiao Tong

Accident date: 23RD DECEMBER 2020

Estimated repair cost for vehicle no: SKX7959G AUDI A4

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>He m</i>		\$2,552.10
2	2	Rear Boot Lid lamp	\$655.00	\$1,310.00
3	1	Rear Boot Lid emble logo		\$82.00
4	1	Rear Boot Lid Number Plate		\$50.00
5	2	Rear Boot Lid Number Plate lamp	\$45.00	\$90.00
6	2	Rear Boot Lid Number Plate lamp		\$324.00
7	1	Rear Boot Lid Inner Lock		\$238.00
8	1	Rear Boot Lid Inner Lock switch		\$550.00
9	1	rear Boot Lid inner lock sensor		\$244.00
10	1	Rear boot lid inner rubber		\$88.00
11	1	Rear Boot Lid towing cover	\$746.00	\$1,492.00
12	2	Rear Boot Lid tail lamp		\$59.00
13	1	Rear boot lid A4 logo		\$59.00
14	1	rear boot Lid 1.8 logo		\$1,760.00
15	1	Rear bumper <i>Defound</i>		\$940.00 470
16	4	Rear bumper reverse sensor <i>2 pieces dmd</i>	\$235.00	\$250.00
17	2	Rear Bumper Side Bracket <i>curled</i>	\$125.00	\$710.00
18	1	Rear bumper reinforcement <i>Dented</i>		\$330.00
19	2	Rear bumper reinforcement bracket <i>He m</i>	\$165.00	\$60.00 30
20	10	Rear bumper clips <i>New</i>	\$6.00	\$890.00
21	1	Rear end panel <i>Repair</i>		\$285.00
21	1	Rear end Panel Top garnish <i>He m</i>		

Subtotal :- \$12,363.10

Labour charges

To remove & re-fix front & rear reverse sensor

~~\$150.00~~ 50

To remove & re-fix cushion

\$120.00

To Check Wiring System

~~\$60.00~~ 30

Tuff kote

\$120.00

Panel beating

\$600.00 250

Spray painting

\$600.00 250

Subtotal :- \$1,650.00

Total:- \$14,013.10