



新福德車廠私人有限公司

A19  
00

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

30/12/2020

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

Accident date: 30/12/2020

Estimated repair cost for vehicle no: GBJ1545L NISSAN NV200 1.5 MT 19'

CHASSIS: VSKYBAM20Z0174415

S/n	Qty	Items / Nett	U/price	Amount
①	1	Front Bonnet <i>Dented</i>		882 \$1,157.90 ✓
2	2	Front Bonnet Hinge <i>Bent</i>	\$57.70	\$115.40 ✓
3	1	Front Bonnet Lock <i>Damaged</i>		\$78.70 ✓
4	1	Front Bonnet Insulation <i>crushed</i>		\$286.50 ✓
5	10	Front Bonnet Insulation Clip <i>new</i>	\$6.50	\$65.00 30 ✓
6	2	Front Head Lamp <i>crushed</i>	\$446.40	\$892.80 ✓
7	2	Front Head Lamp Lower Bracket <i>Not new</i>	\$75.70	\$151.40 ✓
8	1	Front Bumper <i>Distorted</i>		\$589.70 ✓
9	2	Front Bumper Side Retainer <i>new</i>	\$35.20	\$70.40 ✓
10	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30 ✓
11	2	Front Bumper Top Side Cover <i>Missing</i>	\$362.20	\$724.40 ✓
12	1	Front Bumper Centre Garnish <i>Not new</i>		\$231.00 X ✓
13	1	Front Bumper Reinforcement <i>Bent</i>		\$614.90 ✓
14	2	Front Bumper Reinforcement Bracket <i>Not new</i>	\$91.70	\$183.40 X ✓
15	2	Front Bumper Fog Lamp <i>new</i>	\$185.50	\$371.00 + ✓
16	1	Front Grille <i>crushed</i>		\$338.00 ✓
17	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20 ✓
18	1	Front Grille Emblem Logo <i>new</i>		\$73.50 ✓
19	1	Front Grille Lower Moulding <i>Not new</i>		\$205.50 + ✓
20	1	Front Support Panel <i>Distorted</i>		395 \$1,057.00 ✓
21	1	Front Support Panel Top Cover <i>Not new</i>		\$145.30 X ✓
22	1	Front Support Panel Air Duct Cover <i>Rehd</i>		\$129.20 ✓
23	1	Front Radiator Tank <i>crushed</i>		\$94.60 ✓
24	1	Front Wiper Garnish <i>Not new</i>		\$277.20 X ✓
25	2	Front Fender <i>Rit Buckled</i>	\$504.70	\$1,009.40 504.70 ✓
26	2	Front Fender Cowling <i>Not new</i>	\$142.80	\$285.60 X ✓
27	15	Front Fender Cowling Clip <i>Not new</i>	\$6.50	\$104.00 X ✓
28	2	Front Horn <i>7 piece damaged</i>	\$98.80	\$197.60 ✓

98.80

29	1	Front Battery Bracket	new		\$127.10	+	
30	1	Front Battery Tray	new		\$38.20	X	
31	1	Front Fuse Box (Small)	new		\$197.10	+	
32	1	Front Air Cleaner Box Assy	cracked	455	\$566.40	✓	
33	1	Front Engine Lower Cover	new		\$272.30	+	
34	2	Front Chassis	Repair		\$742.60	\$1,485.20	+

6423.60  
5781.24  
Subtotal:- \$12,252.70  
Spare Part Discount - 10% :- \$11,027.43

S/n	Qty	Items / Special Nett	U/price	Amount	
35	1	Front Wiper Tank	185	\$247.90	+
36	1	Front Battery		\$155.00	+
37	1	Front Fuse Box (Small)		\$360.00	+
38	1	Front Radiator		\$687.40	✓
39	1	Front Radiator Fan Motor	317	\$685.90	✓
40	1	Front Radiator Tank		\$186.90	+
41	1	Front Air-Con Condenser		\$653.00	✓
42	1	Front Air-Con Air Duct Blower Assy		\$508.40	+
43	1	Front Air-Con Coolant Coil Blower Assy		\$1,101.40	+
44	1	Front Fan Belt		\$43.40	+
45	1	Front Alternator		\$1,889.80	✓
46	1	Front Air-Con Compressor		\$1,121.10	✓
47	1	Front Air-Con Compressor Pipe		\$251.30	+
48	2	Front Air-Con Compressor Bracket		\$108.80	+
49	1	Front Intercooler		\$2,121.60	-
50	1	Front Intercooler Hose		\$859.90	+
51	3	Front Engine Mounting		\$203.50	+
52	1	Front Compressor		\$1,656.30	+
53	1	Front Fan Motor Resistor Relay		\$335.60	+
54	1	Front Fan Motor Resistor Relay Backet		\$65.00	+

Subtotal :- \$13,242.20

6984.90  
6286.41

**Labour charges**

To remove & refit front dashboard	\$300.00 *
To remove & refit front windscreen	\$120.00 *
Gum	\$50.00 *
To remove & refit air-con blower, coolant coil, air duct blower & top up gas	\$280.00 *
To remove & refit air-con condenser, radiator, fan motor & top up gas	<del>\$280.00</del> 120
To remove & refit front R/H door, glass, gear motor, lock, rubber & trim board	\$180.00 *
To remove & refit front engine	\$550.00 *
To remove & refit front undercarriage	\$280.00 *
To remove & refit front steering rack & crossmember	\$380.00 *
To repair chassis member	\$450.00 *
To check wiring	<del>\$100.00</del> 30
To check wheel alignment	\$150.00 *
Towing Fee	<del>\$150.00</del> 60
Panel beating	<del>\$3,000.00</del> 1100
Spray painting	<del>\$2,400.00</del> 1100

2410

Subtotal :- \$8,670.00

Total:- \$32,939.63

Supplementary 1: 551.70  
 Supplementary 2: 243

15272.35

total: 15272.35  
 CP/P)

Adrian Lj  
 P/P 04/01/21  
 08 Dany  
 N.V. Anthonse



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

07/01/2021

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

Accident date: 30/12/2020

Estimated repair cost for vehicle no: GBJ1545L NISSAN NV200 1.5 MT 19'

CHASSIS: VSKYBAM20Z0174415

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Front Air-Con Section Pipe <i>Best</i>		\$278.00 ✓
2	1	Front Air-Con Discharge Pipe <i>Best</i>	<i>335</i>	\$415.90 ✓

Subtotal :- \$693.90

*613*  
Supplementary 1: *551.70*

*Adnan Lj*  
*06/01/20*  
*sl/s*



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

09/01/2021

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 30/12/2020

Supplementary repair cost for vehicle no: GBJ1545L NISSAN NV200 1.5 MT 19'

CHASSIS: VSKYBAM20Z0174415

S/n	Qty	Items / Special Nett	U/price	Amount
1	2	Front Support Panel Side Panel <i>Dishted</i>	\$255.00	270 <i>\$510.00</i>
2	2	Front Bumper Fog Lamp Housing <i>cut # 14</i>	\$115.00	\$230.00
Subtotal :-				<u>\$740.00</u>

*Adnan G  
P/P 09/01/21  
H/S*

*270  
Supplementary 2: 243*