

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 06 Jan 2021

Preliminary Advice

Vehicle No	: GBJ1545L	Accident Date	: 30/12/2020
Make	: NISSAN NV200	Policy No.	: 2000001818
Assignment Date	: 03/01/2021	Excess	: S\$800.00
Date of Inspection	: 04/01/2021	Est. Duration of Repair	: 8
Inspection At	: NEW HOCK TECK MOTOR WORKSHOP (HQ) BLK 1, KAKI BUKIT AVENUE 6 #01-43, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,939.63
Revised Amount	:S\$	12,046.83
Check Items (Estimated)	:S\$	8,601.31
Total	:S\$	20,648.14
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	11,463.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,537.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :