


## AUTOTEAM ENGINEERING PTE LTD

No. 7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K

bizSAFE<sub>3</sub>



### INVOICE

#### Bill To

#### SBS Transit Ltd

Ang Mo Kio Workshop

15 Ang Mo Kio Street 63

Singapore 569117

Attn: Finance Dept

Invoice No. IN20121732

Date 7 Jan 2021

P/O No. SBST0000010783

Terms Net 30

S/No	Description	Qty	Unit Price	Amount
	<b><u>Repair Accident Bus - SBS 8298G</u></b>			
1.	Supply 3 workers (9 Working Hours)	1	S\$450.00	S\$450.00
-	Replace Right Side Headlamp Cover			
-	Repair Left Side Headlamp Cover			
-	Repair Front Bumper			
-	Spray Painting Left & Right Side Headlamp Cover			
-	Spray Painting Front Bumper			

Comments

Total

S\$450.00

All cheques should be crossed and made payable to  
**AUTOTEAM ENGINEERING PTE LTD**

Issued By

