



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 20.12.2020
Emailed : 19.01.2021, 11am
Date Survey : 04.01.2021

VEHICLE NO : SLW 8483 Z
MODEL : MIT OUTLANDER 2.0
WIP : 61008

Material	:	\$	<u>1,507.66</u>
Labour	:	\$	<u>1,480.00</u>
Sub-Total	:	\$	<u>2,987.66</u>
REPAIR LIMIT	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>2,387.66</u>
GST 7%	:	\$	<u>167.14</u>
Grand Total	:	\$	<u>2,554.80</u>
Finalise By/Date	:	<u>LOI / 19/01/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 05/01/2021	Cust No/Name	/Justin Blaze S/O George
	Reg No/Reg Date	SLW8483Z / 06/03/2018
	Date In/Mileage	05/01/2021/ 71295
	Chassis/Package	GF7W0401220 /#
	Engine No	4J11XN8735
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/01/2021/ 14:46	BLE	260 / AiTing	61008			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH REAR DOOR, REPAIR LH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 450.00
E PNT98000 RESPRAY ON LH REAR DOOR, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
E PNT88000 REMOVE & REINSTALL LH REAR DOOR COMPONENTS TO NEW PANEL								✓ 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
X EXC EXCESS								-600.00
X PANEL ASSY,RR DOOR,LH					1.00	✓ 937.00	23.00	721.49
X GARNISH,RR DOOR,LH					1.00	✓ 164.00	23.00	126.28
X AIR DAM,SIDE,LH					1.00	✓ 541.00	23.00	416.57
X TAPE,RR DOOR SASH					1.00	✓ 42.00	23.00	32.34
X TAPE,RR DOOR SASH					1.00	✓ 42.00	23.00	32.34
X MOULDING,RR WHEEL ARCH,LH					1.00	✓ 199.00	23.00	153.23
X W/STRIP,R/DR OPN,LWR OTR L → Supply					1.00	33.00	23.00	25.41
Z TEXT AIG OD CLAIM DOA : 20.12.20 SURVEYOR STEVE LKK 04.01.21 POLICY NO: 1800020683 , REPAIR 04 DAYS								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	1,507.66	Nett	2,387.66
Labour	1,420.00	7% GST on	167.14
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	2,554.80
Diagnostics Job	0.00		
Sundry/Others	-540.00		
Total(w/o GST)	2,387.66		



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLW 8483 Z**

<u>Materials</u>		<u>Cost (\$)</u>
1	W/Strip, R/Dr opn, Lwr otr L	33.00 / TN

Total		33.00
Less 23% discount		7.59
Total after discount		25.41
7% GST		1.78

Grand total		<u>\$ 27.19</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

SLW8482Z
Data very noisy, not unit to Base all 50 send
Job Done

2021.01.11

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2017MY

All DTCs

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs		
	AUTO CRUISE	GAS_0E640000		Non-target System		
	4WS/Electric Power Steering	EPS_45880040		No DTCs		
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
	SRS-AIR BAG	ORC_81047302		No DTCs		
	Air Conditioner	AC_80080011		No DTCs		
	ETACS	ETACS_83040801		No DTCs		
	Meter	MTR_84084001		No DTCs		
	Steering Angle Sensor	GS_SAS_47000100		Non-target System		
	AND	AND_8C080002		Non-equipped System or Communication Error		
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
	LIN	ETACS_83040801		Non-target System		
	Power Gate	ETG_92080000		Non-equipped System or Communication Error		

All DTCs

2021.01.11

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs			
	OSS	OSS_9588000B		No DTCs			
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error			
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error			
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error			
	Gateway	GW_C1000000		Non-equipped System or Communication Error			
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error			
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error			
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error			