

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/SUZANA BTE ABDUL RAHIM	
Ltd.	Reg No/Reg Date		
MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING	Date In/Mileage		
	Chassis No	MMBSTA13AKH003433	
SINGAPORE 079120	Engine No	3A92UJB2056	
Contact No 6419 1892	Make/Mode1	MIT/19MY ATTRAGE 1.2 CVT	
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	04/01/2021/ 09:51	QUK	282 / Kevin Leong		61392		
		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000			MANAGEMENT MATERIAL SOCIETY					2250.00
REPLACE	FRI BUMPE	R, BONNET, FRT RH FE WHEEL HOUSING	NDER & AF	FECTED AREA				
E PNT98000	N FKI KH	WHEEL HOUSING						
Service of the property of the property of the service of the serv	RK ON FRI	BUMPER BONNET ERT	DH EENDE	R, FRT RH WHEEL HOUSI	NC.			2450.0
, FRT RH	DOOR, BO	DY KIT & RH WING MIR	ROR COVER	K, FKI KH WHEEL HOUST	NG			
M SUNDRY			TON COVER					80.0
PERFORM	RUST PREV	'ENTION						80.0
A 54900099								30.0
1 1000000		MASSIS ELECTRICAL SYS						
A 10028901	OUT DIAG	NOSTIC CHECK HEINC &	T OCAN TO	imai	1 _			120.0
USING HI	-SCAN PRO	TEST CHECKLUSTING	T-27 WIN BK	1115/2015	7/0			
M SUNDRY	oonii i iio		2) [[110			400.0
TO APPLY	ZERTONA	COATING ON AFFECTED	AREA					400.0
M SUNDRY							- 4	50.0
SUNDRIES	1001/ 011							
M HEADLAMP		r II			1.00	660.00		508.2
M LAMP ASSY M FACE,FR E		Ln			1.00	303.00		233.3
M MARK, THRE					1.00	703.00 69.00		541.3
M GRILLE, FR					1.00	165.00		53.1 127.0
M AIR DAM,					1.00	18.00		13.8
M BRACKET,					1.00	13.00		10.0
M GARNISH,	R BUMPER	,RH			1.00	127.00		97.7
M HOOD M HINGE,HOO	חם חו				1.00	734.00	A STATE OF THE PARTY OF THE PAR	565.1
M HINGE, HOO	The state of the s				1.00	56.00		43.1
M FENDER, FF					1.00	56.00 497.00		43.1
M REINFORCE		BUMPER			1.00	466.00		382.6 358.8
M SHIELD, FF	WHEELHO	USE,RH			1.00	98.00		75.4
M COVER, DOC		,OTR RH			1.00	114.00		87.7
M EMBLEM EC	0				1.00	17.00		17.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Co Reg No : 197701469G

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING	Cust No/Name	/SUZANA BTE ABDUL RAHIM		
	Reg No/Reg Date			
	Date In/Mileage			
	Chassis No	MMBSTA13AKH003433		
SINGAPORE 079120	Engine No	3A92UJB2056		
Contact No 6419 1892	Make/Model	MIT/19MY ATTRAGE 1.2 CVT		
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Contract l	
KAX00008	Credit	04/01/2021/ 09:51	QUK	282 / Kevin Leong		61392		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M UNPAINTE		ΓS /SIG,FR RH			1.00 1.00	1643.00 129.00	20.00	1314.40 99.33



Confirm & accepted by

Nett 9,951.56 7% GST on 9951.56 696.61

Total Payable 10,648.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.