



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EU TEIK LEONG Reg No/Reg Date SKU341BT / 21/07/201 Date In/Mileage 04/01/2021/ 0 Chassis No KNAFX411MF5448649 Engine No G4FGFH776547 Make/Model KIA/FORTE K3 1.6 A EX W/ LED & D.BR Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	04/01/2021/ 11:28	QUK	282 / Kevin Leong	26681			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT PANEL & AFFECTED AREA								420 1200.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL								350.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								120.00
M SUNDRY TO TOP UP AIRCON GAS								80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								120.00
M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES								20 50.00
M LAMP ASSY-HEAD,RH					1.00	1870.00	20.00	1496.00
M LAMP ASSY-HEAD,LH					1.00	1870.00	20.00	1496.00
M CARRIER ASSY-FRONT END MODULE					1.00	776.00	20.00	620.80
M RADIATOR ASSY					1.00	546.00	20.00	436.80
M BLOWER ASSY					1.00	606.00	20.00	484.80
M GUARD-AIR,RH					1.00	19.00	20.00	15.20
M GUARD-AIR,LH					1.00	19.00	20.00	15.20
M COVER-FR BUMPER					1.00	728.00	20.00	582.40
M GRILLE ASSY-RADIATOR					1.00	322.00	20.00	257.60
M MOULDING-FRT BPR LICENSE PLATE					1.00	21.00	20.00	16.80
M LIP ASSY-FRONT BUMPER					1.00	54.00	20.00	43.20
M STRIP ASSY-FR BUMPER UPR					1.00	33.00	20.00	26.40
M GARNISH-RADIATOR GRILLE,UPR					1.00	48.00	20.00	38.40
M MOULDING-FRONT BUMPER A/INTAKE					1.00	104.00	20.00	83.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	97.00	20.00	77.60
M STIFFNER-FR BPR LWR					1.00	131.00	20.00	104.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EU TEIK LEONG Reg No/Reg Date SKU3418T / 21/07/201 Date In/Mileage 04/01/2021/ 0 Chassis No KNAFX411MF5448649 Engine No G4FGFH776547 Make/Model KIA/FORTE K3 1.6 A EX W/ LED & D.BR Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	04/01/2021/ 11:28	QUK	282 / Kevin Leong	26681		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	RAIL ASSY-FR BUMPER			1.00	410.00	20.00	328.00
M	BRACKET-FR BUMPER SIDE MTG,LH			1.00	13.00	20.00	10.40
M	BRACKET-FR BUMPER SIDE MTG,RH			1.00	13.00	20.00	10.40
M	LOGO ASSY-KIA SUB			1.00	51.00	20.00	40.80

# Estimate

Steve (LKK) 00- N/A Ad  
4/1/21, 12:00pm EX cess - ?  
P/P

My Bel SJ  
5 & dys

9974.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed

Confirmation accepted by be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

7% GST on **Nett** 8,184.80  
Total Payable **8,757.74**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.