

JEC AUTO SERVICE

1 Kaki Bukit Ave 6 #02-11 Autobay, Singapore 417883.

Hp : 9232 7457

Tel : 6509 6585

Email : jecautoservice@yahoo.com.sg

TPAXA

Veron.

Fax : 6509 6584

Vehicle No : FBH 4938C

Model : Yamaha 135

Qty	List Price		Price
1	Front fender <i>Defect</i>	\$	65.00 ✓
1	Front cowling <i>ut</i>	\$	98.00 ✓
1	Front cowling inner garnish <i>xcen</i>	\$	75.00 +
2	Fork inner tubes <i>Bent</i>	\$	190.00 ✓
2	Fork outer tubes	\$	200.00 ✓
1	Front sport rim <i>New</i>	\$	280.00 +
1	Fork under bracket <i>Bent</i>	\$	185.00 ✓
1	Front rim shaft <i>New</i>	\$	38.00 +
1	Front brake disc <i>New</i>	\$	155.00 +
1	Handle bar	\$	85.00 +
1	Handle bar end <i>ut</i>	\$	48.00 ✓
1	Handle bar bracket <i>xcen</i>	\$	85.00 +
2	Side mirrors <i>ut</i>	\$	76.00 ✓
2	Front signal lamps <i>LH ut</i>	\$	100.00 50
1	Top cowling <i>ut</i>	\$	85.00 ✓
1	Headlamp <i>ut</i>	\$	65.00 ✓
1	Meter assy <i>xcen</i>	\$	290.00 x
2	Side cowlings <i>LH ut</i>	\$	210.00 105
1	Side cowling inner garnish <i>xcen</i>	\$	48.00 +
1	Front footrest bracket <i>Bent</i>	\$	42.00 ✓
1	Front footrest rubber <i>ut</i>	\$	22.00 ✓
1	Rear footrest <i>Bent</i>	\$	45.00 ✓
1	Rear footrest bracket <i>ut</i>	\$	65.00 ✓
1	Exhaust <i>xcen</i>	\$	220.00 x
1	Exhaust chrome cover <i>xcen</i>	\$	125.00 x
1	Front brake lever <i>Bent</i>	\$	28.00 ✓
1	Rear brake pedal <i>xcen</i>	\$	65.00 x
Subtotal :			\$ 2,990.00

1369

1232-10

Special Nett Items :

1	Number plate	ATE new	\$	28.00	✓
2	Fork oils	3x new	\$	30.00	✓
2	Fork oil seals		\$	56.00	✓
1	Steering cone	New	\$	75.00	✓
1	Rear box	ut	\$	185.00	✓
1	Rear box bracket	new	\$	145.00	✓
1	Front tyre	3x new	\$	125.00	✓
1	Sticker		\$	90.00	✓
Subtotal :			\$	734.00	

Labour Charges :

To provide transport service charge	\$	45.00	✓
To remove ,refit and alignment of body frame	\$	350.00	200
To provide labour charges ,workmanship to dismantle above damaged parts ;re-align body structure and damaged consistent to the accident.	\$	480.00	200
Subtotal :	\$	875.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 4,599.00

445

total: 2023 10.

H/S: 16K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: