

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21000046/Avd3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 30/03/2021	
			Code	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGJ 3631Z	Veh. Inspected	SLD 3398U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008546/KY	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	31/12/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VELLFIRE	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JTNGF3DH908004365	Colour	BLACK	
	Odometer	181840 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/55 R18	HABILEAD	6 mm	
	L/H Front Tyre	235/55 R18	HABILEAD	6 mm	
	R/H Rear Tyre	235/55 R18	HABILEAD	6 mm	
	L/H Rear Tyre	235/55 R18	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/12/2020	Inspection Date	31/12/2020	
	Survey held at ISHARE AUTO PTE. LTD.				
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: