

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 31.12.20

TO : AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS
VEHICLE NO : SLD3398U
MODEL : TOYOTA VELLFIRE
DATE OF ACCIDENT : 30.12.20
TIME OF ACCIDENT : 18:15HRS

Veron.

J7NGF3DH908004365

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 790.00	\$ 790.00
2	REAR BUMPER BRACKET <i>Not in</i>	2	\$ 98.00	\$ 196.00
3	REAR BUMPER SIDE UPPER GARNISH <i>could</i>	2	\$ 276.00	\$ 552.00
4	REAR BUMPER TOW HOOK COVER <i>Not in</i>	1	\$ 22.00	\$ 22.00
5	REAR BUMPER SIDE RETAINER (FRONT) <i>Not in</i>	2	\$ 98.00	\$ 196.00
6	REAR BUMPER SIDE RETAINER (REAR) <i>Not in</i>	2	\$ 99.00	\$ 198.00
7	REAR BUMPER SIDE INNER GARNISH <i>Dehd</i>	2	\$ 158.00	\$ 316.00
8	REAR BUMPER SENSOR <i>Not in</i>	2	\$ 498.00	\$ 996.00
9	REAR BUMPER SENSOR WIRE HARNESS <i>Not in</i>	1	\$ 299.00	\$ 299.00
10	TAILGATE <i>Dented</i>	1	\$ 2,460.00	\$ 2,460.00
11	TAIL GATE AUTO SIDE SENSOR <i>Not in</i>	1	\$ 1,095.00	\$ 1,095.00
12	TAIL GATE EMBLEM 'VELLFIRE' <i>Not in</i>	1	\$ 115.00	\$ 115.00
13	TAILGATE BUZZER <i>could</i>	1	\$ 290.00	\$ 290.00
14	TAILGATE INNER HOLDER <i>Not in</i>	1	\$ 85.00	\$ 85.00
15	TAILGATE STOPPER <i>Not in</i>	2	\$ 35.00	\$ 70.00
16	TAILGATE DAMPER <i>Not in</i>	2	\$ 245.00	\$ 490.00
17	TAILGATE TOP LOCK <i>Dented</i>	1	\$ 768.00	\$ 768.00
18	TAILGATE LOWER LOCK <i>Not in</i>	1	\$ 68.00	\$ 68.00
19	TAILGATE INNER TRIM <i>could</i>	1	\$ 1,295.00	\$ 1,295.00
20	TAILGATE WEATHER STRIP <i>Not in</i>	1	\$ 392.00	\$ 392.00
21	TAILGATE WINDSCREEN C/W MOULDING <i>Not in</i>	1	\$ 1,795.00	\$ 1,795.00
22	REAR FENDER COWLING <i>Not in</i>	2	\$ 165.00	\$ 330.00
23	REAR FENDER INNER TRIM <i>Not in</i>	2	\$ 796.00	\$ 1,592.00
24	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 299.10	\$ 299.10
25	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 920.00	\$ 920.00
26	REAR FLOOR PANEL <i>Not in</i>	1	\$ 1,210.00	\$ 1,210.00
27	REAR SEAT RAILWAY <i>Not in</i>	2	\$ 896.00	\$ 1,792.00

Handwritten notes and marks on the right side of the table, including checkmarks, crosses, and numerical values like 1856, 116, 524, 708, 798, and 798.

TO : AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS
 VEHICLE NO : SLD3398U
 MODEL : TOYOTA VELLFIRE
 DATE OF ACCIDENT : 30.12.20
 TIME OF ACCIDENT : 18:15HRS

28	REAR SEAT RAILWAY COVER GARNISH	2	\$ 164.00	\$ 328.00
29	REAR RAILWAY CENTER TRAY	1	\$ 293.00	\$ 293.00
30	REAR RAILWAY CENTER TRAY COVER BOARD	1	\$ 257.00	\$ 257.00
31	REAR STORAGE COVER BOARD	1	\$ 189.00	\$ 189.00
32	REAR FLOOR MATT	1	\$ 1,042.00	\$ 1,042.00
33	REVERSE CAMERA	1	\$ 1,106.00	\$ 1,106.00
34	REAR EXHAUST PIPE	1	\$ 1,890.00	\$ 1,890.00
35	REAR EXHAUST GASKET (SET)	1	\$ 120.00	\$ 120.00
36	REAR EXHAUST MOUNTING	6	\$ 49.00	\$ 294.00

7746.10
5809.57

TOTAL PRICE \$ 24,150.10
 LESS 25% \$ 6,037.53
SUB TOTAL PRICE \$ 18,112.58

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00
3	REAR BUMPER SIDE UPPER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
4	REAR BUMPER SIDE INNER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
5	REAR BUMPER REFLECTOR (SPECIAL TYPE)	1	\$ 180.00	\$ 180.00
6	TAIL LAMP CLIP (SET)	1	\$ 40.00	\$ 40.00
7	TAILGATE SEALANT	1	\$ 150.00	\$ 150.00
8	TAILGATE NUMBER PLATE GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
9	TAILGATE INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
10	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
12	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
13	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
14	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 30.00	\$ 30.00
15	REAR END PANEL INSULATION SEAL (OUTER)	1	\$ 150.00	\$ 150.00
16	REAR FLOOR PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
17	REAR FLOOR MATT CLIP (SET)	1	\$ 50.00	\$ 50.00

TOTAL \$ 1,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	1000

TO : **AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SLD3398U**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : **30.12.20**
 TIME OF ACCIDENT : **18:15HRS**

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	900
3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	REMOVE AND REFIX TAILGATE GLASS	\$ 150.00	120
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
11	REMOVE, REFIX AND RESET REAR VIDEO RECORDER	\$ 250.00	30
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
13	REMOVE AND REFIX POWER ARM AND SPEAKER	\$ 250.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL

\$5,000.00

2350

Adnan U
H/s 31/12/20

06 Days

TOTAL PARTS COST : \$ 19,462.58
 TOTAL LABOUR COST : \$ 5,000.00
 TOTAL REPAIR COST : \$ 24,462.58

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PPRICES ARE SUBJECT TO CHANGES.

the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during resurvey

YOURS FAITHFULLY

- Parts prices are subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No illegal modification is allowed
- Surveys must be resurveyed and is subject to final approval from Insurance Company

SERVICE ADVISOR

ABBY

Acknowledged by Repairer

Signature:

total: 8639.57

H/s: 6.8K.

6.8K