



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10919/TAN SENG YIAU
	Reg No/Reg Date	SMN5692S*KC17/ 19/08/201
	Date In/Mileage	/ 0
	Chassis No	KNAF1416MK5049768
	Engine No	G4FGKH744185
	Make/Model	KIA/CERATO 1.6 A L S116
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2020/ 10:29	QUE	261 / Edwin Caina	26573

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR ROOF PNL				2000.00
E PNT98000 RESPRAY ROOF PNL				1100.00
E PNT88000 REMOVE & REFIT ROOF LINING				200.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY FRT WINDSCREEN SEALANT				80.00
E PNT88000 REMOVE & REFIT FRT WINDSCREEN GLASS				240.00
M SUNDRY Sundries				20.00
M MOULDING-WINDSHIELD GLASS	1.00	56.00	20.00	44.80

# Estimate

SURVEYOR NAME: Stere CLKK) OD - NH AL

SURVEYOR SIGNATURE: \_\_\_\_\_  
DATE: 6/1/21, 2.00pm

REMARKS: 4 days

PIP  
By Bel spj

Confirm & accepted by consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

	Nett	3,874.80
7% GST on	3874.80	271.24
<b>Total Payable</b>		<b>4,146.04</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.