

Our Job Ref No : 305445660

Date : 22.01.21

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHD3697D CTPL

31.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** --- **SLK9366K**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

\$1,650.00

Final Lumpsum Repair cost

\$1,650.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Signature :

Name : LIM KWOK ENG

Name :

Tel : 62148316

Date :

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2021)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3697D/02/01/2021 14:14**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	de ✓ *1,106.00 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	ny ✓ *22.00 FL
3	1		*REAR BUMPER SPONGE	20.00	0.00	? *119.50 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *428.40 FL
5	1		*REAR BUMPER LOWER COVER	20.00	0.00	di ✓ *228.00 FL
6	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	ny ✓ *135.70 F
	1		*REAR BUMPER MAT	0.00	0.00	ny ✓ *50.00 F
8	1		*REAR PANEL ASSY	20.00	0.00	X *526.70 FL
9	1		*REAR PANEL TRIM-TRANSVERSE TOP	20.00	0.00	X *57.60 FL
10	1		*BOOTLID ASSY	20.00	0.00	X *2,174.90 FL
11	1		*BOOTLID LATCH ASSY	20.00	0.00	X *114.90 FL
12	1		*BOOTLID EMLEM - I40	20.00	0.00	X *67.90 FL
13	1		*BOOTLID EMLEM - CRDI	20.00	0.00	X *52.40 FL
14	1		*BOOTLID COMFORTDELGRO LOGO CTPL	0.00	0.00	X *30.00 F
15	1		*BOOTLID TEL NO STICKER CTPL	0.00	0.00	X *30.00 F
16	1		*REAR BUMPER ADVERTISEMENT LOGO	0.00	0.00	ny ✓ *50.00 F
17	1		*REAR FENDER ADVERTISEMENT LOGO LH	0.00	0.00	ny ✓ *100.00 F
18	1		*REAR FENDER ADVERTISEMENT LOGO RH	0.00	0.00	ny ✓ *100.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	5,394.00
- List Item Discount on L Items (\$\$)	979.66
Total Parts (\$\$)	4,414.34

ComfortDelGro Engineering Pte Ltd/SHD3697D/02/01/2021 14:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1,356
- 20%
1,084.80
+ Net 435.70
1,520.50

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

2 SPRAY PAINTING CHARGE

3 REVE/REFIX REVERSE SENSOR

New

New

New

850.00

650.00

120.00

Gross Labour Cost (S\$)

1,620.00

ComfortDelGro Engineering Pte Ltd/SHD3697D/02/01/2021 14:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9749 5749
WP 4/1/2020 10am

LLS. Repair after repair \$1,650/-
2 days
Tanpin Efficiency