

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



04 JAN 2021

GST REG. NO : M2 - 0020081 - X

ESTIMATE

VEHICLE IN

Estimate No. : b1 57087
Date Estimated : 02/01/2021
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Pramodh Rai
325 Jurong East Street 31
#12-186

Singapore 600325

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME2541L	WBAJG120403G76288	24/09/2018	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper panel and attachments, rear spoiler,
rework bootlid, rear right side panel

/ 2550 4,250.00

To respray rear bumper, bootlid, rear spoiler, rear
right side panel

/ 3005 3,339.00

To replace rear windscreen glass.

/ 574 676.00

To conduct water leak tests.

/ 63 75.00

To supply and install rear windscreen solar film.

m/x 451 531.00

To check electrical wiring system and lighting at the
rear section for proper function.

/ 150 177.00

Sundries

net / ? 150.00

vacuum glass debris

/ 190 224.00

Total Labour 1: 9,422.00

DESCRIPTION

SCREW SELF TAPPING
RR BUMPER CARRIER
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER LH MOUNT (M)
REAR BUMPER RH MOUNT (M)
MOUNTING SMART OPENER (M)
REAR BUMPER PANEL PRIMED (M/PDC)
REAR BUMPER TRIM PANEL BOTTOM (M/PO)
LETTERING S DRIVE 18i
LETTERING X1
BUMP STOP
REAR WINDOW (ESG)

QTY	PRIC
2	1.20
1	496.35
1	143.35
1	143.35
1	162.25
1	162.25
1	45.75
1	1,191.60
1	297.80
1	97.15
1	64.75
10	3.20
1	851.00

VALUE

net 2.40
7. 496.35
x 143.35
p. 143.35
x 162.25
p. 162.25
? 45.75
de 1,191.60
de 297.80
NEC 97.15
net 64.75
net 32.00
cum 851.00



Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57087
Date Estimated : 02/01/2021
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME2541L	WBAJG120403G76288	24/09/2018	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
HOOK AND LOOP FASTENER	10	2.85	28.50
AEROBLADE (SCHWARZ)	1	393.50	393.50
REAR RH LIGHT IN TRUNK LID	1	277.10	277.10
REAR RH LIGHT IN THE SIDE PANEL	1	399.85	399.85
DECOUPING RING PDC TORQUE CONVERTER	4	5.15	20.60
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

Total Parts : 5,098.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 5/1/21 @ 11:30 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97475749 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Tan Jiah @ Performance.com

No. of Working Days Recommend 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	9,422.00
Parts	:	5,098.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,016.46
Grand Total	:	15,537.26