

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

19th December 2020

WONG FU HONG

Blk 3 Kaki Bukit Road 1

03 - 04 Eunost Technolink

Singapore 415935

TP ALG.
Jasper.

Accident date: 17th DEC 2020

Estimated repair cost for vehicle no: SLC4177P TOYOTA VIOS 1.5A '2016

S/n	Qty	Items	U/price	Amount
1	1	bootlid		\$895.00
2	2	Rear tail lamp	\$312.20	\$624.40
3	4	Rear tail lamp clips	\$12.90	\$51.60
4	1	Rear Bumper		\$455.20
5	2	Rear Bumper Side Bracket	\$131.70	\$263.40
6	2	Rear Bumper retainer	\$185.20	\$370.40
7	2	rear bumper beam		\$128.00
8	1	Rear Bumper Reinforcement		\$352.00
9	1	Rear Bumper reverse sensor		\$300.00
10	8	Rear bumper clips	\$12.90	\$103.20
11	1	Rear number plate		\$50.00

613.20

Subtotal :-

\$3,593.20

459.80

S.N. 200

Labour charges

\$120.00

To Remove & refix cushion

\$120.00

To Remove & refix reverse Sensor

\$120.00

Tuff kote

\$60.00

To Check Wiring System

\$400.00

Panel beating

\$400.00

Spray painting

Subtotal :-

\$1,220.00

Total:-

\$4,813.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1139.90

L/S: 900

02 Days