

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III21000083/APA3Q2

Date: 24/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005521_01
Claimant Vehicle No : SML490B **Insured Vehicle No :** GX8128D
 Date of Loss: 24/12/2020 Nature of Claim: TP Claim No: MFL2020D0002825

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML490B**
 Make & Model: AUDI A7, 2.0 TFSI LED (A) Engine No: CYP086683
 Reg. Date: 26/10/2018 (Man. Year: 2017) Chassis No: WAUZZZ4G3JN036016
 Colour: Silver Odometer: 29253 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19 Rear Tyre Size: 255/40 R19
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,509.85	18,429.51	11,080.34	37.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,290.00	2,320.00	64.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,119.85	19,719.51	13,400.34	40.46
Approved Total (Overridden) (S\$)		15,700.00		
(S\$)	33,119.85	15,700.00	17,419.85	52.60
+ GST 7.00/7.00% (S\$)	2,318.39	1,099.00	1,219.39	52.60
Nett Amount (S\$)	35,438.24	16,799.00	18,639.24	52.60
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		17,406.45		

INSPECTION

Date of Assignment: 28/12/2020
 Date Inspected: 28/12/2020 Inspected At: Mg Solution Pte Ltd - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4 #04-01
 Singapore 41800
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2021)
Parts:	143	AUDI A7 2.0 TFSI LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML490B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	4,255.60 FL	*- FL
2	1		*FRONT BUMPER	Torn	2,968.00 FL	*2,968.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	Cracked	230.60 FL	*44.00 FL
4	1		*FRONT BUMPER SENSOR	Not Necessary	420.00 FL	*- FL
5	1		*FRONT FENDER RH	Dented	1,355.60 FL	*1,355.60 FL
6	1		*FRONT FENDER INNER COWLING	Torn	455.60 FL	*275.00 FL
7	1		*HEADLAMP RH	Cracked	12,647.00 FL	*12,647.00 FL
8	1		*FRONT SHOCK ABSORBER RH	Not Necessary	942.60 FL	*- FL
9	1		*FRONT WHEEL HUB RH	Damaged	897.40 FL	*468.00 FL
10	1		*FRONT LOWER ARM RH	Bent	1,079.30 FL	*539.00 FL
11	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,267.50 FL	*- FL
12	1		*FRONT KNUCKLE ARM BEARING RH	Damaged	547.30 FL	*547.30 FL
13	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
14	1		*SET FRONT FENDER INNER COLWING CLIPS	Necessary	35.00 FS	*35.00 FS
15	1		*WHEEL TYRE	Cut	580.00 FS	*400.00 FS
16	1		*SET WHEEL RIM	Cut	4,500.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,216.50	20,313.90
- List Item Discount on L Items 10.00/10.00% (S\$)	2,706.65	1,884.39
Total Parts (S\$)	29,509.85	18,429.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	500.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	180.00	30.00
5	WHEEL ALIGNMENT	New	100.00	80.00
6	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	280.00	180.00
Gross Labour Cost (\$\$)			3,610.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >