

Date: 04.01.2021
Vehicle No: SLG9539A
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106532322-2016
Reg.Year: 2016

Third Party Insurer: MSIG
Third Party Veh No: YP9924S
Date of Accident: 01.01.2021

*Not Authorized
61 Sup 82350p
Recovery After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT FENDER RH	1		<i>By</i> \$477.70	✓
2	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>na</i> \$48.30	✓
3	FRONT FENDER INNER SHIELD RH	1		<i>DI</i> \$216.90	✓
4	FRONT SIDE MIRROR ASSY	1	<i>Del / CM</i>	\$857.60	✓
5	FRONT DOOR RH <i>1005.90</i>	1		<i>By</i> \$1,241.00	✓
6	FRONT TYRE RH	1		<i>h</i> \$240.00	X
7	FRONT WHEEL RIM RH	1		<i>By</i> \$263.70	X
8	FRONT WHEEL CAP RH	1		<i>h</i> \$180.60	X
9	FRONT ABSORBER RH	1		<i>h</i> \$463.20	X
10	FRONT LOWER ARM RH	1		<i>h</i> \$457.80	X
11	FRONT KNUCKLE ARM RH	1		<i>h</i> \$594.60	X
12	FRONT WHEEL BEARING RH	1		<i>na</i> \$168.90	X
13	FRONT TIE ROD END RH	1		<i>h</i> \$186.70	X
14	REAR DOOR RH	1		<i>h</i> \$1,045.00	X
15	REAR BUMPER	1	<i>(N.C.) Del</i>	\$878.70	X
16	REAR BUMPER SIDE BRACKET RH	1		<i>h</i> \$64.40	X
17	FRONT SIDE A-PILLAR RH	1		REPAIR	
18	REAR FENDER RH	1		REPAIR	
SUB TOTAL				\$7,385.10	
LESS 25%				-\$1,846.28	
PARTS TOTAL				\$5,538.83	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>na</i> \$30.00	✓
2	REAR BUMPER CLIPS	1		<i>na</i> \$50.00	X
S/N TOTAL				\$80.00	