

Date: 04.01.2021
Vehicle No: SLG9539A
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106532322-2016
Reg.Year: 2016

Third Party Insurer: MSIG
Third Party Veh No: YP9924S
Date of Accident: 01.01.2021

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR
ACCIDENT AREAS & ETC.

4001
\$1,200.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT
FRONT FENDER RH, FRONT DOOR RH, FRONT SIDE A-PILLAR RH, REAR DOOR RH,
REAR FENDER RH, REAR BUMPER & ETC.

4601
\$1,300.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT ABSORBER RH, FRONT LOWER
ARM RH, FRONT KNUCKLE RH & ETC.

22 \$200.00 X

TO WHEEL ALIGNMENT & BALANCING.

22 \$80.00 X

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR RH INNER
MECHANISM & ETC. TO EFFECT REPLACE OF FRONT & REAR DOOR RH.

\$240.00 601

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 201

LABOUR TOTAL	\$3,100.00
--------------	------------

TingAn

TOTAL	\$8,718.83
-------	------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 150143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

