

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6229 H

| | | | |
|------|------------------------------|----------|-------------------|
| 1 pc | Rear bumper | \$ | 696.00 <i>Rx</i> |
| 1 pc | Rear bumper side bracket o/s | \$ | 29.00 <i>X M</i> |
| 1 pc | Rear o/s wheel cover | \$ | 116.00 <i>X M</i> |
| | | \$ | 841.00 |
| | | Less 10% | \$ 84.10 |
| | | \$ | 756.90 |

S/NETT

| | | | |
|-------|--|----|---------------------|
| 1 set | Rear bumper clips | \$ | 48.00 <i>X M</i> |
| 1 pc | Rear bumper top protector | \$ | 80.00 <i>X M</i> |
| 1 pc | Rear o/s fender sticker | \$ | 60.00 <i>net</i> |
| 1 set | o/s door stickers | \$ | 100.00 <i>X M</i> |
| 1 set | o/s rocker panel garnish clips | \$ | 38.00 <i>X M</i> |
| | Sundry | \$ | 50.00 <i>X M</i> |
| | To check rear o/s wheel alightment | \$ | 80.00 <i>X M</i> |
| | To dismantle / replace reverse sensor to new bumper and reset to the same | \$ | 120.00 <i>30</i> |
| | To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear o/s door, rear o/s rocker panel garnish, etc | \$ | 850.00 <i>300</i> |
| | To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, rear o/s rocker panel garnish | \$ | 800.00 <i>400</i> |
| | To apply rustproofing on the repaired and replaced panels. | \$ | 120.00 <i>30</i> |
| | | \$ | 3,102.90 <i>760</i> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taylor 97495749
WP 4/1/21 @ 520pm
Resurvey after repair.
tanji @ (khan)son.
2 days
9820
2 day #